Report No. : DH1509080007A Version : B



## TEMPORARY IMMERSION AND DUST TEST REPORT

Company : <u>AAEON Technology Inc.</u>

Address : 5F, No. 135, Lane 235, Pao Chiao Rd., Hsin-Tien Dist,

New Taipei City, 231, Taiwan, R.O.C.

Model Name : AIOT-QM SERIES

Date Received : SEP 09, 2015

Date Tested : <u>SEP 09, 2015 ~ SEP 10, 2015</u>

#### **TESTING LABORATORY IS ACCREDITED BY:**

IEC/IECQ 17025 certificate of independent test laboratory approval

Certificate No.: 1.72.0031

ISO 17025 accredited in respect of laboratory is approved by TAF

Certificate No.: L0835-140329

ISO 9001 certificate is approved by TUV CERT certification body of TUV NORD Cert GmbH

#### **WE HEREBY CERTIFY THAT:**

The test(s) shown in the attachment were conducted according to the indicating procedures. We assume full responsibility for the accuracy and completeness of these tests and vouch for the qualifications of all personnel performing them.

790740	Name	Signature	Date
Test Engineer	Andy Ku	Andy ku	Sep 21, 2015
Manager	Injel Chen	Injel Chen	Sep 21, 2015

#### NOTE:

1. This report will be invalid if reproduced in part or altered in any wa

2. This report refers only to the specimen(s) submitted to test, and is in a judget of the control of the contr

3. This report is ONLY valid with the examination seal and signature of this insti-

 The tested specimen(s) will only be preserved for thirty days from collected by the applicant.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

#### Report No.: DH1509080007A Page 1 of 10

#### **TABLE OF CONTENTS**

1. GENERAL INFORMATION	
1.1 DESCRIPTION OF UNIT	2
1.2 UNIT OPERATING CONDITION	2
2. TEMPORARY IMMERSION TEST	
2.1 TEST EQUIPMENT	3
2.2 LABORATORY AMBIENCE CONDITION	3
2.3 REFERENCE DOCUMENT	3
2.4 TEST CONDITION	3
2.5 SUMMARY OF TEST	3
3. DUST TEST	
3.1 TEST EQUIPMENT	4
3.2 LABORATORY AMBIENCE CONDITION	4
3.3 REFERENCE DOCUMENT	4
3.4 TEST CONDITION	4
3.5 SUMMARY OF TEST	4
ATTACUMENTO	_



Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

#### Report No.: DH1509080007A

Page 2 of 10

#### 1. GENERAL INFORMATION

#### 1.1 DESCRIPTION OF UNIT

Manufacturer : AAEON Technology Inc.

Model name: AIOT-QM SERIES

Test item and Sample quantity: (Total of 2 units)

Test item	Sample quantity	
Temporary immersion test	1 unit	
Dust test	1 unit	

#### 1.2 UNIT OPERATING CONDITION

None



Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

#### Report No.: DH1509080007A Page 3 of 10

#### 2. TEMPORARY IMMERSION TEST

#### 2.1 TEST EQUIPMENT

Model	Calibration Date
ETL-L180 Water Leakage Test Chamber	NCR

#### 2.2 LABORATORY AMBIENCE CONDITION

Temperature: 25 °C ± 10 °C

Relative humidity: 50 % ± 25 % (RH)

#### 2.3 REFERENCE DOCUMENT

This test is based on IEC/EN 60529 IPX7 temporary immersion Test Protected. (2013)

#### 2.4 TEST CONDITION

Unit is non-operating.

The water temperature is +25 °C

The lowest point of unit is locating 1000 mm below surface of the water.

The duration of test is 30 minutes

#### 2.5 SUMMARY OF TEST

After testing, visual inspection showed no water permeated into the unit (the inner unit was dry).



Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

### 3. DUST TEST

#### 3.1 TEST EQUIPMENT

Model	Serial Number	Calibration Date
Vötsch VDT 1000A	59566059640010	DEC 13, 2014

#### 3.2 LABORATORY AMBIENCE CONDITION

Temperature: 25 °C ± 10 °C

Relative humidity: 50 % ± 25 % (RH)

#### 3.3 REFERENCE DOCUMENT

The test is based on IEC/EN 60529 IP6X Dust Test Protected. (2013)

#### 3.4 TEST CONDITION

Unit is non-operating.

Dust material: Talcum powder (100% dry fine)

Particle size	Amount (%)
< 5 µm (Diameter)	42.31%±5
5~10 μm (Diameter)	35.85%±5
10~20 µm (Diameter)	21.15%±5
20~40 µm (Diameter)	0.69%±5
> 40 µm (Diameter)	0%

Amount of talcum power: 2 kg/m3 (chamber volume)

Dust density: 2.03 g/cm3

Depression level: 20 mbar

Air direction: Vertically to achieve slowest possible downward settlement

Duration of exposure: 8 hours

#### 3.5 SUMMARY OF TEST

After testing, visual inspection showed no dust particles permeated into the unit.

Report No.: DH1509080007A

Page 4 of 10



Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C. Tel: 886-3-579-9909, Fax: 886-3-610-0399


http://www.istgroup.com

Report No.: DH1509080007A

Page 5 of 10

#### Attachment 1: Photo of temporary immersion test setup







Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

#### Report No.: DH1509080007A

Page 6 of 10

#### Attachment 2: Photo of dust test setup

#### Setup



**Before testing** 

After testing











Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C. Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: DH1509080007A

Page 7 of 10

#### Attachment 3: Photo of unit before and after temporary immersion test

#### **Before testing**

Function was normal



#### After testing

Function was normal





Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C.

Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

#### After testing


Report No.: DH1509080007A

Page 8 of 10

No water permeated into unit









Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C. Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: DH1509080007A Page 9 of 10

#### Attachment 4: Photo of unit before and after dust test

#### **Before testing**

#### Function was normal



#### After testing

#### Function was normal



# INTEGRATED SERVICE TECHNOLOGY

#### Integrated Service Technology Inc.

Reliability & Failure Analysis Engineering Group 1F, No.19, Pu-ding Rd., Hsin - chu City, Taiwan, R.O.C. Tel: 886-3-579-9909, Fax: 886-3-610-0399

http://www.istgroup.com

Report No.: DH1509080007A

Page 10 of 10

#### After testing

No dust particle permeated into unit



