

UL International Services Ltd.--Taiwan
Branch
4th Floor
No. 260 Da-Yeh Road
Pei Tou, Taipei, Taiwan 112
Telephone: 886-2-2896-7790
Fax: 886-2-2891-7644
Email: ul.tw@tw.ul.com



AARON TECHNOLOGY INC
5TH FL
135 LANE 235 PAO CHIAO RD
NSIN-TIEN
TAIPEI TAIWAN

Date: 03/10/2004
Subscriber: 368202001
File No: E231775
Project No: 04CA09076
PD No: 04004261
Type: R
PO Number: ARTHUR CHEN

Subject: Procedure Material For Manufacturer

The following material resulting from the investigation under the above numbers is enclosed.

<u>Document</u>	<u>Status</u>	<u>Volume</u>	<u>Report Reference</u>	<u>Date</u>
Index		XI		
UL Test Report	New	XI	E231775-AS-UL-1	03/09/04

Please file revised Authorizations, Indices, and General Inspection Instructions in place of material of like identity. New Test Reports should be filed immediately following the last Test Report. Amendments or Corrections should be filed immediately before the Test Report to which they relate. Re-issued Test Reports should be filed immediately before all material related to the Test Report that it replaces.

NOTE: Manufacturers receive only the following sub-sections of the Applicant's complete Test Report, where applicable: Cover Page, Specific Inspection Criteria (BA through BE), Specific Technical Criteria (through section CF), Critical Components table, and Enclosures containing image supplements. Manufacturers do not receive Test Report Information related to standard clause compliance or testing results.

Please review this material and report any inaccuracies to JESSICA CHEN (886-2-2896-7790), referring to the above Project and/or PD Numbers.

UL INSPECTION CENTER 818

A not-for-profit organization
dedicated to public safety and
committed to quality service