

UL International Services Ltd.  
Branch  
4th Floor  
No. 260 Da-Yeh Road  
Tai Tou, Taipei, Taiwan 112  
Telephone: 886-2-2896-7790  
Fax: 886 2-2891-7644  
Email: ul.tw@tw.ul.com



*Mr. L. Titmes*  
ARCON TECHNOLOGY INC  
5TH FL  
135 LANR 235 PAO CHIAO RD  
HSTN-TIKN  
TATPEI TAIWAN

Date: 06/16/2003  
Subscriber: 369202001  
File No: F231775  
Project No: 03CA17436  
PD No: 03C08872  
Type: 3  
EC Number: 920516LC1

Subject: Procedure Material For Manufacturer

The following material resulting from the investigation under the above numbers enclosed.

<u>Document</u>	<u>Status</u>	<u>Volume</u>	<u>Report Reference</u>	<u>Date</u>
Index UL Test Report	New	x2 x2	E231775-M-UL-1	06/13/03

Please file revised Authorizations, Indices, and General Inspection Instructions place of material of like identity. New Test Reports should be filed immediately following the last Test Report. Amendments or Corrections should be filed immediately before the Test Report to which they relate. Re-issued Test Reports should be filed immediately before all material related to the Test Report that replaces.

NOTE: Manufacturers receive only the following sub-sections of the Applicant's complete Test Report, where applicable: Cover Page, Specific Inspection Criteria (through BE), Specific Technical Criteria (through section CF), Critical Component table, and Enclosures containing image supplements. Manufacturers do not receive Test Report Information related to standard clause compliance or testing results.

Please review this material and report any inaccuracies to CHARLIE WU (886-2-2896-7790), referring to the above Project and/or PD Numbers.

UL INSPECTION CENTER 818