


# BOXER-6640

Supplier: POKI / Carton size: 412(L)\*306(W)\*285(H) mm

## Package Drop Test Report



Summary	<p><input checked="" type="checkbox"/> <b>PASS</b></p> <p><input type="checkbox"/> <b>Fail</b> Note : There is/are ___ defect(s) not list in the report, please check it in the DTS Website.</p> <p><input type="checkbox"/> <b>Pass with Deviation</b></p>
---------	---

Issue date

2017-06-16

Approval

Tony Liang

Test Engineer

Terry Huang

# Test item list

---

1. *Test item list* ----- 2
2. *Configuration of EUT* ----- 3
3. *Package drop test* ----- 5

## Testing Result


Num	Test item list	Result	Remark
1	Package drop test	Pass	

# Configuration of EUT

Num	Item	Device Information
1.	Model Name	BOXER-6640
2.	M/B Name	PBA-SKS02
3.	BIOS / Version	R0.2
4.	CPU	Intel Kaby-lake i7-7700TE
5.	Memory Type	SEC 649K4A8G085W8
6.	2.5" SATA HDD	TOSHIBA MQ01AAD010C 100G
7.	Test Software	Windows 8 / Run PassMark Burn In Test 8.1 Pro
8.	Adapter	FSP / FSP060-DBAB1 12V 5A MAX




## Photos

### After Test





# Package Drop Test



# Package Drop Test

**Test Date:** 06-17-2017

**Test Product:** BOXER-6640

**Test Site:** PO KI PAPER CONTAINER. ,LTD

**Test Standard:**

Reference ISTA PROJECT 1A

**Test Equipment:**

Drop Tester


KING DESIGN Co. LTD

Model: KD-128A

Serial Number: UU110099185

**Test Condition:**

1. Test Phase: One corner. Three edges. Six face
2. Test Cycle: 1 Cycle
3. Test Height: 76cm
4. Test Weight:6.6Kg
5. Sample Package: 1unit in single-package.
6. Test Drawing:



**Test Result:**

The EPE had crack, but the structure is OK, System no structure deformation and function was working normally after drop test.