

BOXER-6640M

Supplier: POKI / Carton size: 412(L)*306(W)*285(H) mm

Package Drop Test Report



Summary	<p><input checked="" type="checkbox"/> PASS</p> <p><input type="checkbox"/> Fail Note : There is/are ___ defect(s) not list in the report, please check it in the DTS Website.</p> <p><input type="checkbox"/> Pass with Deviation</p>
---------	---

Issue date

2017-06-16

Approval

Tony Liang

Test Engineer

Terry huang

Test item list

1. *Test item list* ----- 2
2. *Configuration of EUT* ----- 3
3. *Package drop test* ----- 5

Testing Result


Num	Test item list	Result	Remark
1	Package drop test	Pass	

Configuration of EUT




Num	Item	Device Information
1.	Model Name	BOXER-6640M
2.	M/B Name	PBA-SKS03 / Ver.B0.1
3.	BIOS / Version	B640MM02
4.	CPU	Skylake-S core i7-6700TE
5.	Memory Type	M4S0-AGS1O5SJ-26-16GB.DDR4 2400 x 2
6.	2.5" SATA HDD	TOSHIBA MQ01AAD010C 100G
7.	Test Software	Windows 8 / Run PassMark Burn In Test 8.1 Pro
8.	Adapter	19V 6.32A

Photos

After Test



Package Drop Test



Package Drop Test

Test Date: 06-17-2017

Test Product: BOXER-6640M

Test Site: PO KI PAPER CONTAINER. ,LTD

Test Standard:

Reference ISTA PROJECT 1A

Test Equipment:

Drop Tester


KING DESIGN Co. LTD

Model: KD-128A

Serial Number: UU110099185

Test Condition:

1. Test Phase: One corner. Three edges. Six face
2. Test Cycle: 1 Cycle
3. Test Height: 76cm
4. Test Weight:6.6Kg
5. Sample Package: 1unit in single-package.
6. Test Drawing:



Test Result:

The EPE had crack, but the structure is OK, System no structure deformation and function was working normally after drop test.