

NOTICE OF COMPLETION AND AUTHORIZATION TO APPLY THE UL MARK

2014/05/02

Aaeon Technology Inc Mr. Sean Hsu 5th Fl 135 Lane 235 Pao Chiao Rd Hsin-tien Dist New Taipei 231, Tw

Our Reference:File E231775, Vol. X2Project Number4786385177Your Reference:L0165k01-AProject Scope:part 1 of 2: UL/CUL for Fanless Embedded Controller, Model:xAEC-6611x (x - Where x may
be any combination of alphanumeric characters or "-"or blank.)

REPORT E231775-A64-UL, NEW

Dear Mr. Sean Hsu:

Congratulations! UL's investigation of your product(s) has been completed under the above Reference Number and the product was determined to comply with the applicable requirements. This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Mark at authorized factories under UL's Follow-Up Service Program. To provide your manufacturer(s) with the intended authorization to use the UL Mark, you must send a copy of this notice to each manufacturing location currently authorized under File E231775, Vol. X2 and *including any special instructions as indicated in the addendum to this letter*.

Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent in the near future. Until then, this letter authorizes application of the UL Mark for 90 days from the date indicated above.

Additional requirements related to your responsibilities as the Applicant can be found in the document "Applicant responsibilities related to Early Authorizations" that can be found at the following web-site: http://www.ul.com/EAResponsibilities

Any information and documentation provided to you involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL.

We are excited you are now able to apply the UL Mark to your products and appreciate your business. Feel free to contact me or any of our Customer Service representatives if you have any questions.

Very truly yours,

Stephen Ho +886 2 28967790 Project Engineer Stephen.Ho@ul.com

CC:,

NBK953D-3EBE64

Reviewed by:

William R. Carney 847/664-1088 Chief Engineer Director I William.R.Carney@ul.com