



**UL International, L.L.C.**  
**Taiwan Branch**

**美商優力安全認證有限公司台灣分公司**

UL International, L.L.C. Taiwan Branch

台北市 112 北投區大業路 260 號 1 樓

1st Fl 260 Da-Yeh Road Peitou Taipei City Taiwan 112

電話: 886-2-2896-7790

傳真: 886-2-2891-7644

<http://www.ul.com.tw>

**NOTICE OF AUTHORIZATION TO APPLY THE UL MARK**

August 2, 2006

MR. Morgan Lin  
 Aaeon Technology Inc  
 5th FL 135 Lane 235 Pao Chiao Rd  
 Hsin-Tien, Taipei  
 Taiwan  
 E-mail: [morganlin@aaeon.com.tw](mailto:morganlin@aaeon.com.tw)  
 CC: [sherryl@cerpass.com.tw](mailto:sherryl@cerpass.com.tw)

Reference: File E231775 Project 06CA35607 P.O. Number 1330606113

Product: Operator Panel, Model AOP-8120DT-XX (X = 0-9, A-Z or blank) for UL/C -UL Investigation.

Dear MR. Lin,

Any information and documentation provided to you involving UL Mark services are provided on behalf of Underwriters Laboratories Inc.

UL' s investigation of your product has been completed under the above project number and the subject product was determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Recognized Marking and/or Recognized Component Mark only at the factory under UL' s Follow -Up Service Program to the subject product, which is constructed as described below:

Identical to the subject product, Operator Panel, Model AOP-8120DT-XX (X = 0-9, A-Z or blank), which was submitted to UL for this investigation. The UL Records covering the product will be in the Follow-Up Services Procedure, File E231775, Volume X1. Report Reference E231775-A12-UL-1.

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and all attached material to each manufacturing location as currently authorized in File E231775, Volume X1.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow -Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL' s requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL' s requirements and continued use of the UL Mark may be withdrawn.

Sincerely,  
 Ike Wang

Reviewed by:  
 Wisely Lin

Ike Wang  
 Engineer  
 UL International, L.L.C., Taiwan Branch  
 Tel: (02)28967790  
 Fax: (02)28907451  
 E-mail: [Ike.wang@tw.ul.com](mailto:Ike.wang@tw.ul.com)

Wisely Lin  
 Associate Project Engineer  
 UL International, L.L.C., Taiwan Branch  
 E-mail: [wisely.lin@tw.ul.com](mailto:wisely.lin@tw.ul.com)





NOTICE OF AUTHORIZATION TO APPLY THE UL MARK

2007-10-31

Page 1 of 2

MR. Morgan Lin  
Aaeon Technology Inc  
5th FL 135 Lane 235 Pao Chiao Rd  
Hsin-Tien, Taipei  
Taiwan

Fax number: 2-89191049  
E-mail: morganlin@aaeon.com.tw

Reference: File E231775 Project 07CA50218 P.O. Number 1330709079  
1. Embedded Control PC, Models xxxxAEC-6810-xxxxxxx, xxxxAEC-6820B-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation .  
2. Embedded Control PC, Models xxxxAEC-6910-xxxxxxx, xxxxONYX-6910-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation .  
3. Operator Panel, Models xxxxAOP-8120HT-xxxxxxx, xxxxAOP-8120WT-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation .  
4. 2U LAN Port Rackmount Firewall Platform, Models xxxxFWS-825xx-xxx-xxx-xxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation .  
Product: 5. Operator Panel, Models xxxxAOP-8120DT-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation .  
6. Embedded Controller, Model xxxxAEC-6920-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation .  
7. Embedded Controller, Model xxxxAEC-6850-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation .  
8. Ethernet Operator Panel, Model xxxxAOP-8070HT-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation .  
9. Operator Panel, Model xxxxAOP-8150HT-xxxxxxx, xxxxAOP-8150WT-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation .

Dear MR. Lin,

This letter replaced the previous letter dated October 30, 2007 .

Any information and documentation involving UL Mark services are provided on behalf of Underwriters Laboratories Inc. (UL) or any authorized licensee of UL.

UL' s investigation of your product has been completed under the above project number and the subject product was determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Listing Mark and/or Recognized Marking and/or Recognized Component Mark only at the factory under UL' s Follow-Up Service Program to the subject product, which is constructed as described below:

- Similar to the subject model, which was submitted to UL for this investigation. The UL Records covering the product will be in the Follow-Up Services Procedure, File E231775, Volume X1, X2 and 2:
1. Report Reference No. E231775-A8-UL-1 Amendment 1, changing model names from "AEC-6810-XX and AEC-6820B-XX" to "xxxxxAEC-6810-xxxxxxx and xxxxAEC-6820B-xxxxxxx".
  2. Report Reference No. E231775-A9-UL-1 Amendment 3, changing model names from "xxxxxAEC-6910-xx-xxxx and xxxxONYX-6910-xx-xxxx" to "xxxxxAEC-6910-xxxxxxx, xxxxONYX-6910-xxxxxxx".
  3. Report Reference No. E231775-A10-UL-1 Amendment 2, changing model names from "AOP-8120WT-XX, AOP-8120HT-XX" to "xxxxxAOP-8120HT-xxxxxxx and xxxxAOP-8120WT-xxxxxxx".
  4. Report Reference No. E231775-A11-UL-2, changing model names from "FWS-825" to "xxxxFWS-825xx-xxx-xxx-xxx" and correcting Volume number to Vol. X2.



2007-10-31

Page 2 of 2

5. Report Reference No. E231775-A12-UL-1 Amendment 1, changing model names from "AOP-8120DT-XX" to "xxxxxAOP-8120DT-xxxxxx".
6. Report Reference No. E231775-A13-UL-1 Amendment 1, changing model name from "AEC-6920-XX" to "xxxxxAEC-6920-xxxxxx".
7. Report Reference No. E231775-A14-UL-1 Amendment 1, changing model name from "AEC-6850-Ax" to "xxxxxAEC-6850-xxxxxx".
8. Report Reference No. E231775-A17-UL-1 Amendment 1, changing model name from "xxxxxAOP-8070HT-xx-xxxx" to "xxxxxAOP-8070HT-xxxxxx".
9. Vol. 2, Sec. 1, changing model names from "AOP-8150HT-XX, AOP-8150WT-XX" to "xxxxxAOP-8150HT-xxxxxx, xxxxAOP-8150WT-xxxxxx".

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and a ll attached material to each manufacturing location as currently authorized in File E231775, Volume X1, X2 and 2.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL's requirements and continued use of the UL Mark may be withdrawn.

Sincerely,

Joy Shen

Joy Shen  
Project Handler  
Department: 3013DTAI

Reviewed by:

Jay Hsu

Jay Hsu  
Project Engineer  
Department: 3013DTAI

CC: Cerpess Technology Corp.  
Fax.: [pennyt@cerpass.com.tw](mailto:pennyt@cerpass.com.tw)  
Attn: Ms Penny Tsai