



Computing Platform Service Partner

AGP-3175

With 3.5" SATA HDD

Vibration Test Report

Report NO: 10P030055

Issued by: **Rex Chang** / **11/05/2010**

Engineer Date

Reviewed by: **Jansin Lee** / **11/05/2010**

Sr. Manager Date

Test item list

1. *Test item list* ----- 2
2. *Random Vibration Operation Test* ----- 3

Testing Result

Num	Test item list	Result	Remark
1	Random vibration operation test	Pass	

HDD Kit



Test Date: 10/08/2010

Test Product: AGP-3175

Test Site: AAEON Internal Lab.


Test Standard: Reference IEC68-2-64 Testing procedures
Test Fh: Vibration boardband random test

Test Equipment:

Vibration Simulator System
KING DESIGN Co. LTD.
Model: KD 9363-EM-600F2K-40N20
Serial Number: UU110099090
Date of Calibration: 10/19/2009

Test Condition:

1. Operation
2. Test Acceleration: 1.0 Grms Random
3. Test Frequency: 5-500Hz
4. Test Axis: X, Y, Z axes
5. Test Time: 60min each axis
6. Test Software: Windows XP / Run one Microsoft media player simultaneously.
7. Test Vibration Curve:



Test Result:

The system structure doesn't deformation; Function is passed during system test.