



Computing Platform Service Partner

AHP-1152

With 2.5" SATA HDD

Vibration Test Report

Report NO: 10P030041

Issued by:	Rex Chang	/	10/04/2010
	<hr/>		<hr/>
	Engineer		Date
Reviewed by:	Jansin Lee	/	10/04/2010
	<hr/>		<hr/>
	Sr. Manager		Date

Test item list

1. *Test item list* ----- 2
2. *Random Vibration Operation Test* ----- 3

Testing Result

Num	Test item list	Result	Remark
1	Random vibration operation test	Pass	

Test Date: 2010/10/04


Test Product: AHP-1152

Test Site: AAEON QE Internal Lab.

Test Standard: Reference IEC68-2-64 Testing procedures
Test Fh: Vibration boardband random test

Test Equipment:
Vibration Simulator System
KING DESIGN Co. LTD.
Model: KD 9363-EM-600F2K-40N20
Serial Number: UU110099090
Date of Calibration: 10/19/2009

- Test Condition:**
1. Operation
 2. Test Acceleration: 3.0 Grms Random
 3. Test Frequency: 5-500Hz
 4. Test Axis: X, Y, Z axes
 5. Test Time: 60min each axis
 6. Test Software: Windows XP / Run one Microsoft media player simultaneously.
 7. Test Vibration Curve:



Test Result:

The system structure doesn't deformation; Function is passed during system test.