

AIOT-QG

With Micro SD Card

Vibration Test Report

Report NO: 15D030001



Summary	<p><input checked="" type="checkbox"/> Pass</p> <p><input type="checkbox"/> Fail Note : There is/are ____ defect(s) not list in the report, please check it in the DTS Website.</p> <p><input type="checkbox"/> Pass with Deviation Comment: _____</p>
---------	---

Issue date

2015-06-17

Approval

KJ Wang

Issued by

Rex Chang

Test item list

1. *Test item list* ----- 3
2. *Random Vibration Operation Test* ----- 4

Testing Result

Num	Test item list	Result	Remark
1	Random vibration operation test	Pass	

Configuration of EUT

Client:

Num	Item	Spec
1.	System:	AIOT-QG
	1. Main Board	AIOT- X1000 Rev. B0.4
	2. BIOS	GNU GRUB version 0.97
	3. CPU	Quark™ SoC X1021 400MHz
	4. Memory	On Board 1GB / DDR3 1600 / SAMSUNG.K4B4G0846D-BYK0
	5. SD Card:	MicroSDHC. Transcend.TS4GUSDC10 4GB
	6. Test Software:	Wind River Linux 5.0.1.19 / Run AAEON Burnintest.
2.	Adapter	FSP120-AAB 19V/6.32A 120W

Host: Fusion V2

Num	Item	Spec
1.	System:	Fusion V2
	1. CPU	Intel Cedarview N2800 1.86GHz
	2. Memory	DSL 4GB / DDR3 1333 / Samsung.K4B2G0846
	3. Test Software	WinXP Run PuTTY Rev. 0.63

Random Vibration Operation Test

Test Date: 06-16 ~ 17-2015

Test Product: AIOT-QG (with Micro SD Card)


Test Site: AAEON QE Dept.

Test Standard: Reference IEC68-2-64 Testing procedures
Test Fh: Vibration boardband random test

Test Equipment:
Vibration Simulator System
KING DESIGN Co. LTD.
Model: KD 9363-EM-600F2K-40N20
Serial Number: UU110099090
Date of Calibration: 10/08/2014

Test Condition:

1. Operation
2. Test Acceleration: 1.0Grms Random
3. Test Frequency: 5-500Hz
4. Test Axis: X, Y, Z axes
5. Test Time: 60min each axis
6. Test Software: Client: WinXP Run PuTTY With Host: Wind River Linux 5.0.1.19 / Run AAEON Burnintest.
7. Test Vibration Curve:



Test Result:

The system structure doesn't deformation; Function was passed during system test