

Windows CE Product Certification Report

Release No : 07P010003

Product Model	AOP-8070HT
Product Description	7", WinCE, Ethernet Operator Panel.
Test Reason	<input checked="" type="checkbox"/> New product <input checked="" type="checkbox"/> PCB : GENE-1270 Rev.B1.0 <input checked="" type="checkbox"/> BIOS: N/A <input type="checkbox"/> Renew product <input type="checkbox"/> PCB : <input type="checkbox"/> BIOS: <input type="checkbox"/> Revision change <input type="checkbox"/> PCB : <input type="checkbox"/> BIOS: <input type="checkbox"/> Component:

2007-01-26

Issue date

Wenyuan Yang

Manager

Andrew Ku

Test Engineer

Test result for certification

Default System Configuration	
CPU Type & FSB	Intel PXA270 RISC Processor 520MHz
Memory Type	M-System Mobile DOC 128Mb
LCD Panel	CPT / CLAA070WA03 / 7" 16:9 WQVGA TFT
Touch Control Chipset	AMT/ ON board Philips UCB 1400
Compact Flash	SanDisk 64MB
Keyboard / PS/2 Mouse	LEMEL 5201 / Logitech M-CAA43
Parallel Device	HP Photo Smart P1000 Printer
Operating System	
WinCE .Net(5.0) with full MultiMedia Suite of applications	8070_50e
ActiveSync Version	3.7.1
Free DOS Kernel Version	1.1.23

Start Function Check	Result
1 Programs function Check	Pass
1-2 Command Prompt function Check	Pass
1-3 Internet Explorer function Check	Pass
1-4 Media Player function Check	Pass
1-5 Windows Explorer function Check	Pass
1-6 PenMount TouchPanel function Check	Pass
2 Favorites function Check	Pass
3 Documents function Check	Pass
4 Settings function Check	Pass
4-1 Control Panel Function Check	Pass
4-2 Network and Dial-up Connections function Check	Pass
4-3 Taskbar and Start Menu Properties function Check	Pass
5 Help Contents function Check	Pass
6 Run Function Check	Pass
Command Prompt Function Test	Result
Write in Character	Pass
Copy Character	Pass
Paste Character	Pass
Clear Screen	Pass
Setting Screen Buffer	Pass
Help icon	Pass
Close icon function	Pass
Internet Explorer Function Test	Result
File icon function	Pass
Edit icon function	Pass
View icon function	Pass
Favorites function	Pass

Media Player Function Test	Result
File icon function	Pass
View icon function	Pass
Playback icon function	Pass
Windows Explorer Function Test	Result
File icon function	Pass
Edit icon function	Pass
View icon function	Pass
Go icon function	Pass
Favorites icon function	Pass
Favorites Function	Result
Add to Favorites Function	Pass
Organize Favorites	Pass
Documents Function Test	Result
File icon securely	Pass
Edit icon function	Pass
View icon function	Pass
Format icon function	Pass
Tools icon function	Pass
Settings Function Test – Control Panel Function	Result
Certificates icon function	Pass
Date/Time icon function	Pass
Dialing icon function	Pass
Display icon function	Pass
Input Panel icon function	Pass
Internet Options icon function	Pass
Keyboard icon function	Pass
Mouse icon function	Pass
Network and Dial-up Connections icon function	Pass
Owner icon function	Pass
Password icon function	Pass
PC Connection icon function	Pass
Regional Settings icon function	Pass
Remove Programs icon function	Pass
Storage Manager icon function	Pass
System icon function	Pass
Volume & Sounds function	Pass
Settings Function Test – Network and Dial-up Connections Function	Result
Dial-Up Connection(COM 1)	Pass
Direct Connection (COM1)	Pass
Activesync Function Test	Pass

Settings Function Test – Taskbar and Start Menu Properties	Result
Always on top function	Pass
Auto hide function	Pass
Show Clock function	Pass
Run Function Test	Result
IE explore Application (iesample.exe)	Pass
Explorer Application (explorer.exe)	Pass
Ipconfig Application (ipconfig.exe)	Pass
WINCE load Application (cestart.exe)	Pass
Cmd Application (cmd.exe)	Pass
Control Application (control.exe)	Pass
Peghelp Application (peghelp.exe)	Pass
Repllog Application (repllog.exe)	Pass
Route Application (route)	Pass
Rflush Application (rflush)	Pass
I/O Function Test	Result
COM1	Pass
USB 1&2 Ports	Pass
USB 3&4 Ports	Pass
LAN connector	Pass
Touch Screen of 4 wire connector	Pass
Pen Mount TouchPanel Function Test	Result
Standard Mode	Pass
Advanced	Pass
USB Function Test	Result
USB Mouse	Pass
USB Keyboard	Pass
USB Floppy	Pass
USB HDD(Flash Disk)	Pass
Power Consumption Test	Result
Normal Mode (+9V)	0.67A
Normal Mode (+12V)	0.52A
Normal Mode (+24V)	0.32A