

P5 Verification Test Plan

Release No : 09E010050

Product Model	EPIC-5537WT
Description	AMD LX + CS5536 EPIC Board
Test Configuration	<input checked="" type="checkbox"/> New product <input checked="" type="checkbox"/> CPU Board : EPIC-5537WT A0.2 <input checked="" type="checkbox"/> BIOS : EPIC-5537WT BIOS Rev 1.0(03/03/2009) <input checked="" type="checkbox"/> Carrier Board : N/A <input checked="" type="checkbox"/> Expansion Board : N/A <input checked="" type="checkbox"/> Chipset : <input checked="" type="checkbox"/> CPU : AMD Geode GX-MMX 500MHz <input checked="" type="checkbox"/> North Bridge : AMD Geode LX 800 <input checked="" type="checkbox"/> South Bridge : CS5536 <input checked="" type="checkbox"/> VGA Chipset : AMD Geode LX 800 <input checked="" type="checkbox"/> Audio Chipset : AMD Geode LX 800 <input checked="" type="checkbox"/> Ethernet Chipset : Intel 8255xER PCI Adapter <input checked="" type="checkbox"/> I/O Chipset : SMC SCH3112 <input checked="" type="checkbox"/> TV Chipset : NA <input checked="" type="checkbox"/> SDVO : Only one SDVO port can be used through the SDVO connector. Another is used by Chrontel CH7308B <input checked="" type="checkbox"/> Remark : P5 Report for EPIC-5537WT
<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> Pass with Deviation Comment: _____ _____	

2009/12/04

Issue date

Wenyuan Yang

Manager

Jerry Tsai

Test Engineer

Summary Table of contents :

Summary Table of contents	2
Platform Information	3
1. I/O Peripheral Function Test	4
2. Power Connector Test	6
2.1. Power Consumption Test	7
3. Timer Accuracy Test	8
4. Network HUB / LAN Connection Test	8
5. Hardware compatibility	8
6. O.S. Compatibility Test	13
7. BIOS Function Test	14
8. Performance Test	15

There are 3 test results in this document; they are described as follows:

Pass: Function worked perfectly

Fail: Function failed and must be modified in the next version

N/A: Outside of specification or no test equipment

Platform Information:

Item	Device Information	Test Item
PCB Model / Version	EPIC-5537WT A0.2	
Carrier Board	N/A	
BIOS / Version	EPIC-5537WT BIOS Rev 1.0(03/03/2009)	
CPU Type	Onboard CPU AMD Geode LX800 500MHz	
Memory Type	Onboard DDR 0701VR V58C2512164SAJ5I 512MB	
SATA	N/A	
Primary IDE Master	Seagate ST3160815A 160GB 3.5" IDE HDD	
Primary IDE Slave	ASUS DVD-E818A DVD-ROM	
CRT	ViewSonic E70 17"	
LCD	N/A	
Compact Flash	N/A	
Backplane	N/A	
Riser Card	N/A	
Expansion Board	N/A	
	N/A	
Operating System	[] Linux-RedHat 9.0 or [X] Fedora Core 6	6
	Windows Server 2003 English Version / Standard Edition 5.2.3790	N/A
	Windows Server 2003 English Version /Standard x64 Edition	N/A
	Windows XP Professional English Version V2002 Service Pack 3	1,2,3,4,5,6,7,8
	Windows XP Professional English Version /Standard x64 Edition	N/A
	Windows 2000 Professional English Version V5.00.2195 Service Pack4	N/A
	Windows Server 2000 English Version	N/A
	Windows 98SE English Version V4.10.2222A	N/A
	MS-DOS 6.22 English Version	N/A
Power Supply	ATX Power Supply : N/A	N/A
	AT Power Supply: LEMACS SP2-4300F 300W AT POWER	1,2,3,4,5,6,7,8
	DC Adapter : N/A	N/A

Test Result for Certification

1. I/O Peripheral Function Test

I/O Function	Result			Note
	Pass	Fail	N/A	
Floppy Connector / Driver A:			X	
Primary IDE Master	X			
Primary IDE Slave	X			
Secondary IDE Master			X	
Secondary IDE Slave			X	
Third IDE Master			X	
Third IDE Slave			X	
RAID 0 Function Test			X	
RAID 1 Function Test			X	
SATA1 / Serial ATA Connector 1	X			
SATA2 / Serial ATA Connector 2			X	
SATA3 / Serial ATA Connector 3			X	
SATA4 / Serial ATA Connector 4			X	
Compact Flash – Type I	X			
Compact Flash – Type II	X			
DOC (Disk On Chip)			X	
DOM (Disk On Module) – 40 Pin			X	Transcend / TS512MDOM40V / 512MB / IDE 40 Pin
DOM (Disk On Module) – 44 Pin	X			Transcend / TS512MDOM44V / 512MB / IDE 44 Pin
COM 1-232	X			
COM 2-232	X			
COM 3-232			X	
COM 4-232			X	
COM 2-422			X	
COM 2-485			X	
PS/2 Mouse & Keyboard (Internal)			X	
PS/2 Mouse & Keyboard (External)	X			
Audio Connector	X			
Audio 5.1 Channel / S/P DIF			X	
LPT 1			X	
SIR / 115.2 Kbps			X	
FIR / 4M bps			X	
USB 1/2 Ports	X			
USB 3/4 Ports	X			
USB 2.0 1/2 Ports	X			
USB 2.0 3/4 Ports	X			
DVI Function			X	
DIO Connector	X			
Card Bus			X	
PC/104	X			
PC/104-Plus	X			
PCI-104	X			
CD-In Connector	X			

TFT TTL LCD	X			
TFT LVDS LCD	X			
TV-out / S Terminal			X	
TV-out / AV Terminal			X	
Touch Screen – 8 Wire			X	
Touch Screen – 4/5 Wire			X	
DIMM Slots			X	
Watchdog I/O n			X	
Watchdog Software Control	X			
FAN1 Connector	X			
FAN2 Connector			X	
Express card			X	
Speaker Connector	X			
LCD Backlight Power Connector	X			
DC in Connector			X	
PCI Express Mini Card			X	
Power Button			X	
Battery Connector	X			
Front Panel (CN34)	Result			Notes
	Pass	Fail	N/A	
Power On Button			X	
IDE LED	X			
External Buzzer			X	
On Board Buzzer	X			
Power LED	X			
Reset Switch			X	
Keyboard Lock			X	
Jumpers Function	Result			Notes
	Pass	Fail	N/A	
BIOS write protection Selection and boot Selection			X	
Backlight enable level Selection and LVDS Power Selection	X			
COM1 +12V/+5V/RING Selection			X	
COM2 +5V/RING Selection	X			
Auto Power button Selection and power on selection			X	
Power source selection			X	
FAN Power Selection	X			
CMOS Clear Selection	X			
LCD Brightness and speaker level Selection			X	
Power Connector & Function	Result			Notes
	Pass	Fail	N/A	

Standard AT Power Connector				X	
Standard ATX Power Connector				X	
5V Only Power Connector		X			
DC Adapter				X	
LAN Connector & Function		Result			Notes
		Pass	Fail	N/A	
LAN Link / Speed LED	LAN1	X			
	LAN2	X			
LAN Active LED	LAN1	X			
	LAN2	X			
LAN 10/100 Ethernet		X			
LAN 1G Ethernet				X	
PCI Connector & Function		Result			Notes
		Pass	Fail	N/A	
Mini PCI Slot				X	
PCI Slot				X	
PCI Express x1				X	
Express card				X	

2. Power Consumption Test

Platform Information:

CPU Board	EPIC-5537WT A0.2
Carrier Board	N/A
BIOS	EPIC-5537WT BIOS Rev 0.65(12/08/2008)
Operating System	Windows XP Professional English Version
CRT	ViewSonic E70 17"
LCD	N/A
Compact Flash	N/A
Expansion Board	N/A
	N/A
Chipset Software	AMD Geode(TM) LX Processor Windows(R) XP AES Driver 2.01.00(10/28/2005)
Graphics Media	Advanced Micro Devices Win XP Graphics Driver 3.0.2.0(11/22/2005)
LAN Driver	Intel 825xER PCI Adapter 8.0.43.0(10/30/2006)
Audio Driver	Geode LX Audio Driver WDM 2.3.0.0(3/17/2006)
Touchscreen Driver	N/A
Power Supply	LEMACS SP2-4300F 300W AT POWER

Test Equipment:

Equipment	AC/DC Digital Clamp meter
-----------	---------------------------

Manufacturer	KYORITSU
Model name	2010

Equipment Certified Calibration:

Calibrated Company	KYORITSU
S/N	WO230798 (EM-213)
Calibration Date	Oct. 12, 2008
Next Calibration Date	Oct. 11, 2009

- Test Point:**
1. Power on machine and boot into Windows environment
 2. Run test software: Prime95 to make system heavy loading in order to measure its maximum current
 3. Use KYORITSU 2010 (set as 20A) to measure each current of system different mode

Test Environment	ATX Power: N/A		AT Power: LEMACS SP2-4300F 300W AT POWER		Note
	Model				
CPU	N/A		Onboard CPU AMD Geode LX800 500MHz		
HDD	N/A		Seagate ST3160815A 160GB 3.5" IDE HDD		
RAM	N/A		Onboard DDR 0701VR V58C2512164SAJ5I 512MB		
OS Environment	N/A		Windows XP Professional English Version		
Normal Mode (+5V)	N/A	A	1.95	A	
Suspend Mode (+5V)	N/A	A	1.27	A	
5VSB in Power Off Mode (just for ATX)	N/A	A	-----	A	
5VSB in Power On Mode (just for ATX)	N/A	A	-----	A	
Normal Mode (+12V)	N/A	A	0	A	
Suspend Mode (+12V)	N/A	A	0	A	
Normal Mode (+3.3V) (just for ATX)	N/A	A	-----	A	
Suspend Mode (+3.3V) (just for ATX)	N/A	A	-----	A	
Normal Mode (-12V)	N/A	A	0	A	

Suspend Mode (-12V)	N/A	A	0	A	
Normal Mode (-5V)	N/A	A	0	A	
Suspend Mode (-5V)	N/A	A	0	A	

3. Timer Accuracy Test

System Clock & RTC Clock Test					
Test Method	Margin for error	Result			
		Pass	Fail	N/A	
RTC Clock in Power On Mode	±3 second during 24 hours	X			
RTC Clock in Power Off Mode	±3 second during 24 hours	X			
Watchdog Timer Test		Result			
		Pass	Fail	N/A	
Time-out Interval	10 sec	X			
	60 sec	X			
	255 sec	X			

4. Network HUB / LAN Connection Test

Location		LED Type				Result		
						Pass	Fail	N/A
LAN1~2 LED		Active LED				X		
		Link LED				X		
Location	Speed	HUB Type	Cable Length	HUB Speed	Onboard LAN Speed	Result		
				Pass	Fail	N/A		
		D-Link DGS-1008T	100M	1GBps	100	X		
		Accton DeskTop-3005	100M	100 MBps	100	X		
		SVEC FD916H (10 Mbps HUB)	100M	10 MBps	10	X		
Location	Speed	D-Link DGS-1008T	100M	1GBps	100	X		
		Accton DeskTop-3005	100M	100 MBps	100	X		
		SVEC FD916H (10 Mbps HUB)	100M	10 MBps	10	X		

5. Hardware Compatibility

CPU Compatible Test							
CPU Type	FSB	Prime95 Version	Result				
			Pass	Fail	N/A		
Onboard CPU AMD Geode LX800 500MHz	333MHz	V25.90	X				
Memory Compatibility Test							
Memory Brand	Memory Chipset	Frequency	Size	MemTest86 Version	Result		
					Pass	Fail	N/A

									X
									X
Audio Basic Function Test							Result		
							Pass	Fail	N/A
System Sound							X		
CD_In							X		
CD_In Sound Recorder							X		
Play Sound Recorder							X		
Line Out							X		
Line In							X		
Line In Sound Record							X		
MIC Speaker					Dynamic		X		
					Condenser		X		
MIC Sound Recorder					Dynamic		X		
					Condenser		X		
Audio 5.1 Channel with S/P DIF Function Test							Result		
							Pass	Fail	N/A
2-channel mode for stereo speaker output									X
4-channel mode for 4 speaker output									X
6-channel mode for 5.1 speaker output									X
S/P DIF function Test					Input				X
					Output				X
On Board TV Function Test							Result		
							Pass	Fail	N/A
NTSC				AV Terminal			X		
PAL							X		
NTSC				S Terminal			X		
PAL							X		
On Board LCD Function Test									
TFT LCD	Type				Voltage		Result		
							Pass	Fail	N/A
LVDS	Data Image 7" / 800*480 / 18bit (16:9)				3.3V		X		
	AUO G065VN01 V.0 / 6.5" / 640x480 / 18bit (4:3)				3.3V		X		
	AUO G065VN01 V.0 / 6.5" / 640x480 / 24bit (4:3)				3.3V		X		
	AU B104SN02 / 10.4" / 800*600 / 18bit (4:3)				3.3V		X		
	AU G150XG01 V.0 / 15" / 1024*768 / 18bit (4:3)				3.3V		X		
	AU M150XN07 V.2 / 15" / 1024x768 / 24bit (4:3)				3.3V		X		
	AU M170EG01 / 17" / 1280*1024 / 48bit (4:3)				5V		X		
	Toshiba LTD12EX1S / 1280*768 / 18bit				3.3V		X		
	AU M170XW01 V.1 / 17" / 1280x768 / 24bit (16:9)				5V		X		
	AUO T260XW02 / 26" / 1366x768 / 24bit				5V		X		
	AU M201UN02 V.5 / 20.1" / 1600x1200x48bit				5V		X		
	AUO T370HW01 / 37" / 1920x1080 / 48bit				26V		X		
TTL	Toshiba LTM10C209A / 10.4" / 640*480 / 18bit (4:3)				5V		X		
	NEC NL8060AC31-12 / 12.1" / 800*600 / 18bit (4:3)				3.3/5V		X		

	Sharp LQ121S1DG11 / 12.1" / 800*600 / 18bit (4:3)	3.3V			X
	LG LM151X2-C2TH / 15.1" / 1024x768 / 18bit (4:3)	3.3V			X
	Fujitsu FLC38XGC6V-06 / 15" / 1024*768 / 36bit (4:3)	5V			X

PCI Slot Function (PCI Adapter Card) Test

Model	Type	Result		
		Pass	Fail	N/A
CHAINTECH NVIDIA GeForce4 MX440-8X	VGA Card			X
SC3000 CMI8738/C3DX	Sound Card			X
Takram DC-395U V1.02	SCSI Card			X
I-VIEW CP-1400AS (with Age STD-477FAI CCD)	Capture Card			X
Intel GD82559 10/100 Mbps Fast Ethernet Adapter	LAN Card			X
D-Link DWL-520+ Wireless LAN	LAN Card			X
ADAPTEC 1420SA RoHS 4-Port SATA II RAID	RAID Card			X
LEMEL MD V1456VQH-P2 PCI MODEM Card	Modem Card			X
D-Link DU-520 USB 2.0	USB Hub Card			X

ISA Slot Function Test

Model	Result		
	Pass	Fail	N/A
Creative CT4170 Sound Blaster Sound Card			X
Adaptec AHA-1510/20/22B SCSI Card			X

PCI-Express Function Test

Model	Result		
	Pass	Fail	N/A
SUNIX SATA1414 VER 1.1 PCI-Express x1 SATA Card			X
SksKonnnect SK-9E21D 10/100/1000 Base-T Adapter PCI-Express x1 LAN Card			X
ASUS EAX1600PRO/TD/256M/A (ATI Chipset) PCI-Express x16 VGA Card			X
WinFast PX6200 TC TDH PCI-Express x16 VGA Card			X

SATA HD Compatibility Test

Model	Result		
	Pass	Fail	N/A
Seagate ST380815AS 80GB 3.5" SATA HDD	X		
Seagate ST3160815AS 160GB 3.5" SATA HDD	X		
Western Digital WD1600AAJS-00B4A0 160GB 3.5" SATA HDD	X		

CD/DVD-ROM Compatibility Test

Model	Result		
	Pass	Fail	N/A
Pioneer DVD-ROM DVD-128A	X		
BENQ-DVD 1650V	X		

IDE Cable Function test

IDE Model	Result		
	Pass	Fail	N/A
40 Pin Cable ATA66			X

44 Pin Cable ATA33	X		
80 Pin Cable ATA100			X
USB Function Test			
USB Basic Function Test	Result		
	Pass	Fail	N/A
USB Controller	X		
USB 2.0 Controller	X		
USB Keyboard Support	X		
USB Mouse Support	X		
USB 1.1 Compatible Test	Result		
	Pass	Fail	N/A
USB 1.1 Compatible Test	X		
USB 2.0 Compatible Test	Result		
	Pass	Fail	N/A
USB 2.0 Compatible Test	X		
USB 2.0 Function Test	Result		
	Pass	Fail	N/A
LITEON DX-20A4PU USB-DVD ROM	X		
USB Device Full Loading Test	Result		
	Pass	Fail	N/A
Model			
Mitsumi FLL3.5 D353GUE/FUE	X		
USB HDD 20GB	X		
USB Card Reader	X		
USB Mouse	X		
USB Thumb drive- Sandisk 4G	X		
Floppy Disk Controller Function Test	Result		
	Pass	Fail	N/A
Copy and compare file between C: and A / B:			X
Change Floppy to None value			X
Swap FDD			X
Peripheral Compatibility-Storage Device			
Model	Interface	Result	
		Pass	Fail
FUJITSU MCB3064SS	SCSI		X
IOMega ZIP 100 parallel port	Parallel		X
IOMega ZIP100MB Internal ATAPI Drive	IDE		X
DOC			X
Type-I CF	Fix / PIO Mode	X	
Type-I CF	Fix / UDMA Mode	X	
Digital I/O Connector Test	Result		
	Pass	Fail	N/A
Input Address:		X	
Output Address:		X	

VCC: (5V)		X			
DIO-1 Function Test		X			
DIO-2 Function Test				X	
Adapter Compatibility- Industry Control Card PC/104, PC/104+, PCI-104 Modules					
Interface	Model	Type	Result		
			Pass	Fail	N/A
PC/104	AAEON PCM-5600	Modem Module			X
	AAEON PCM-3115B	PCMCIA Module			X
PC/104+	AAEON PCM-3430	SCSI Module			X
PCI-104	AAEON PCM-FA00	Mini-PCI Converter			X
	AAEON PCM-3794	SCSI Module			X
	AAEON PCM-3730	Intel 82559 LAN Module			X
On-Board RAID Function Test					
Model	Interface	Result			
		Pass	Fail	N/A	
Set SATA HDDs as RAID 0	SATA			X	
Set SATA HDDs as RAID 1	SATA			X	
Set SATA HDDs as RAID 10	SATA			X	
Set SATA HDDs as RAID 5	SATA			X	
COM Function Test		Result			
COM Port Burn In Test overnight		Pass	Fail	N/A	
		X			
Disk On Module [DOM] Compatibility Test					
Model	Interface	Result			
		Pass	Fail	N/A	
Transcend / TS512MDOM40V / 512MB	IDE 40 Pin			X	
Transcend / TS512MDOM44V / 512MB	IDE 44 Pin	X			
Mini PCI Card Compatibility Test					
Model (Use PCI-104 transform board: MBC-1TM Rev.A1.0)	Interface	Result			
		Pass	Fail	N/A	
PER-C10L Mini PCI LAN Card(Intel 82551QM)	LAN			X	
GM-101 WLAN 11b/g 54Mbps Mini PCI Card (Model: VNT6655AM)	LAN			X	
COM/LPT Ports & RS-232/422/485 Function Test		Result			
RS-422 for COM2		Pass	Fail	N/A	
				X	
RS-485 for COM2				X	
COM1		X			
COM2		X			
COM3				X	
COM4				X	

LPT1			X
LPT2			X
Card Bus(PCMCIA) Compatibility Function Test			
Model	Result		
	Pass	Fail	N/A
Intel PRO/Wireless 2011B LAN PC Card (WPC2011BWW)			X
PQI 16MB Compact Flash Adapter (64MB PQI CF Card inserting)			X
Kingston datapack DP-PCM2 / 2GB (PC Card TypeII HDD)			X
PCi GW-NS54SG Cardbus Adapter Wireless LAN Type-II			X

6. O.S. Compatibility Test

Installation Operation System Compatibility Test			Result		
			Pass	Fail	N/A
[] Linux-RedHat 9.0 or [] Fedora Core 4.0 [X] Fedora Core 6.0			X		
Windows Server 2003 English Version / Standard Edition 5.2.3790					X
Windows Server 2003 English Version /Standard x64 Edition					X
Windows Vista 32-bit					X
Windows Vista 64-bit					X
Windows XP Professional English Version V2002 Service Pack 3			X		
Windows XP Professional English Version /Standard x64 Edition					X
Windows 2000 Professional English Version V5.00.2195 Service Pack4					X
Windows Server 2000 English Version					X
Windows 98SE English Version V4.10.2222A					X
DOS 6.22 English Version					X
Utility and Driver Test					
OS	Drivers Version		Result		
			Pass	Fail	N/A
Fedora Core 6.0	Chipset Software	Default driver	X		
	Graphics Media	Default driver	X		
	LAN Driver	Default driver	X		
	Audio Driver	Default driver	X		
Windows Server 2003 English Version Standard Edition 5.2.3790	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X
	Audio Driver	N/A			X
Windows Server 2003 English Version Standard x64 Edition	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X
	Audio Driver	N/A			X
Windows Vista 32-bit	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X

	Audio Driver	N/A			X
Windows Vista 64-bit	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X
	Audio Driver	N/A			X
Windows XP Professional English Version V2002 Service Pack 3	Chipset Software	AMD Geode(TM) LX Processor Windows(R) XP AES Driver 2.01.00(10/28/2005)	X		
	Graphics Media	Advanced Micro Devices Win XP Graphics Driver 3.0.2.0(11/22/2005)	X		
	LAN Driver	Intel 8255xER PCI Adapter 8.0.43.0(10/30/2006)	X		
	Audio Driver	Geode LX Audio Driver WDM 2.3.0.0(3/17/2006)	X		
Windows XP Professional English Version /Standard x64 Edition	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X
	Audio Driver	N/A			X
Windows 2000 Professional English Version V5.00.2195 Service Pack 4	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X
	Audio Driver	N/A			X
Windows Server 2000 English Version	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X
	Audio Driver	N/A			X
Windows 98SE English Version V4.10.2222A	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X
	Audio Driver	N/A			X

7. BIOS Function Test

Test Item	Result		
	Pass	Fail	N/A
Memory Beep Test	X		
Standard CMOS Setup Test	X		
Boot Sequence Test	X		
Power Management Test			
APM Power Management Test	X		
ACPI Power Management Test			X
Power On Function Test	X		
Wake Up Event Test	X		
Power On after Power Failure Test			X
CMOS Backup / Clear CMOS Test	X		
Boot ROM Test (PXE)	X		
Supervisor / User Password Test	X		

LCD Function Test	X		
TV Standard Function Test			X
Init Display First Function Test	X		
On-Chip Serial ATA Function Test			X
SATA Mode-IDE/RAID Function Test			X
PC Health Status			
Voltage Monitor Test	X		
FAN Speed Monitor Test	X		
Temperature Monitor Test	X		
USB Onboard Device Function Test	X		
COM Address / IRQ Test	X		
LPT Address / IRQ Test	X		
BIOS AWDFLASH Program Test	X		

8. Performance Test

Platform Information

CPU Board	EPIC-5537WT A0.2
Carrier Board	N/A
BIOS	EPIC-5537WT BIOS Rev 1.0(03/03/2009)
Operating System	English Windows XP Professional Service Pack 3 V2002
CPU	Onboard CPU AMD Geode LX800 500MHz
Memory	Onboard DDR 0701VR V58C2512164SAJ5I 512MB
SATA HDD	N/A
Primary IDE Master	Seagate ST3160815A 160GB 3.5" IDE HDD
Primary IDE Slave	IBM GCR-8480B
CRT	ViewSonic E70 17"
LCD	N/A
Compact Flash	N/A
Expansion Board	N/A
	N/A
Chipset Software	AMD Geode(TM) LX Processor Windows(R) XP AES Driver 2.01.00(10/28/2005)
Graphics Media	Advanced Micro Devices Win XP Graphics Driver 3.0.2.0(11/22/2005)
LAN Driver	Intel 8255xER PCI Adapter 8.0.43.0(10/30/2006)
Audio Driver	Geode LX Audio Driver WDM 2.3.0.0(3/17/2006)
Touchscreen Driver	N/A
Power Supply	LEMACS SP2-4300F 300W AT POWER

Test result:

Testing Software	Result	Unit
------------------	--------	------

PCMark2002		
CPU	608	
Memory	1592	
HDD	357	
Final Reality V1.01—BenchMark Test		
2D image	4.05	
3D	0.48	
Bus transfer	8.13	
Overall	2.70	Reality marks
3Dmark2001		
3Dmark2001SE Build 330_Benchmark mode	N/A	

Test Result:

Testing Software	Result	Unit
PCMark05		
PCMark	N/A	PCMarks
CPU	301	
Memory	N/A	
Graphics	N/A	
HDD	N/A	
3Dmark2003 v360		
3Dmark Score	N/A	
CPU Score	N/A	