

# P5 Verification Test Plan

Release No : 08P010011

Product Model	<b>FOX-120</b>
Description	<b>Multi-Purpose &amp; Weather-Resistant Panel PC with 12 TFT LCD</b>
Test Configuration	<input checked="" type="checkbox"/> New product <input checked="" type="checkbox"/> System: FOX-120 <input checked="" type="checkbox"/> PCB : GENE-8310 Rev:A1.11 <input checked="" type="checkbox"/> BIOS : FOX-120 BIOS Rev 1.0 (7/7/2008) <input checked="" type="checkbox"/> Chipset : <input checked="" type="checkbox"/> North Bridge : Intel 852GM <input checked="" type="checkbox"/> South Bridge : Intel ICH4 <input checked="" type="checkbox"/> VGA Chipset : Intel 852GM integrated VGA <input checked="" type="checkbox"/> Audio Chipset : Realtek ALC655 <input checked="" type="checkbox"/> Ethernet Chipset : Intel 82562 10/100Mb <input checked="" type="checkbox"/> I/O Chipset : IT8712IX  <input checked="" type="checkbox"/> Remark : QE P5 Report for FOX-120
<b>Test Result Summary</b>	
<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> Pass with Deviation  Comment: _____ _____	

*2008/07/08*

**Issue date**

*Wenyuan Yang*

**Manager**

*Allen Hsu*

**Test Engineer**

## Summary Table of contents :

Summary Table of contents	2
Platform Information	3
1. I/O Peripheral Function Test	4
2. Power Connector Test	7
3. Timer Accuracy Test	7
4. Network HUB / LAN Connection Test	7
5. Hardware compatibility	8
6. O.S. Compatibility Test	13
7. BIOS Function Test	15
8. Performance Test	16

There are 3 test results in this document; they are described as follows:

**Pass:** Function worked perfectly

**Fail:** Function failed and must be modified in the next version

**N/A:** Outside of specification or no test equipment

**Platform Information:**

Item	Device Information	Test Item
PCB Model	FOX-120	
BIOS / Version	FOX-120 BIOS Rev 1.0 (7/7/2008)	
CPU Type	Intel Celeron M processor 1.5GHz	
Memory Type	Apacer PC3200 DDR 266 1GHz	
SATA HDD	N/A	
Primary IDE Master	FUJITSU MHV2040AC IDE 40G	
Primary IDE Slave	N/A	
CRT	N/A	
LCD	Sharp LQ121S1LG61	
Compact Flash	N/A	
PCI-104	N/A	
Backplane	N/A	
Operating System	[ X ] Linux-RedHat 9.0 or [ ] Fedora Core 4.0 [ ] Fedora Core 7.0	N/A
	Windows Server 2003 English Version / Standard Edition 5.2.3790	N/A
	Windows Server 2003 English Version /Standard x64 Edition	N/A
	Windows XP Professional English Version V2002 Service Pack 2	N/A
	Windows XP Professional Simplified-Chinese Version V2002 Service Pack 3	1,2,3,4,5,6,7,8
	Windows XP Professional Japanese Version V2002 Service Pack 2	N/A
	Windows XP Professional English Version /Standard x64 Edition	N/A
	Windows 2000 Professional English Version V5.00.2195 Service Pack4	1,3,4,5,6,7,8
	Windows 2000 Professional Simplified-Chinese Version V5.00.2195 Service Pack4	N/A
	Windows 2000 Professional Japanese Version V5.00.2195 Service Pack4	N/A
	Windows Server 2000 English Version	N/A
	Windows 98SE English Version V4.10.2222A	N/A
	MS-DOS 6.22 English Version	N/A
Power Supply	ATX Power : N/A	N/A
	AT Power : N/A	N/A
	DC Power: SINPRO MPU100-108	1,2,3,4,5,6,7,8

## Test Result for Certification

### 1. I/O Peripheral Function Test

I/O Peripheral Function Test –I/O Function	Result		
	Pass	Fail	N/A
Floppy Connector / Driver A:			X
Primary IDE Master	X		
Primary IDE Slave			X
Secondary IDE Master			X
Secondary IDE Slave			X
Third IDE Master			X
Third IDE Slave			X
RAID 0 Function Test			X
RAID 1 Function Test			X
SATA1 / Serial ATA Connector 1			X
SATA2 / Serial ATA Connector 2			X
SATA3 / Serial ATA Connector 3			X
SATA4 / Serial ATA Connector 4			X
Compact Flash – Type I			X
Compact Flash – Type II			X
DOC (Disk On Chip)			X
DOM (Disk On Module) – 40 Pin			X
DOM (Disk On Module) – 44 Pin	X		
COM 1-232	X		
COM 2-232	X		
COM 2-422	X		
COM 2-485	X		
COM 2-Ring /+5V /+12V			X
COM 3-232			X
COM 4-232			X
COM 5-232			X
COM 6-232			X
PS/2 Mouse & Keyboard (Internal)			X
PS/2 Mouse & Keyboard (External)			X
Audio Connector			X
Audio 5.1 Channel / S/P DIF			X
LPT 1			X
LPT 2			X
SIR / 115.2 Kbps			X
FIR / 4M bps			X
USB 1/2 Ports	X		
USB 3/4 Ports			X
USB 5/6 Ports			X
USB 2.0 1/2 Ports	X		
USB 2.0 3/4 Ports			X
USB 2.0 5/6 Ports			X

DVI Function			X
DIO Connector			X
Card Bus			X
PC/104			X
PC/104-Plus			X
PCI-104			X
CD-In Connector			X
TFT TTL LCD			X
TFT LVDS LCD			X
TV-out / S Terminal			X
TV-out / AV Terminal			X
Touch Screen – 8 Wire			X
Touch Screen – 5 Wire			X
DIMM Slots	X		
Watchdog IRQ n			X
Watchdog Software Control	X		
CPU FAN Connector			X
System FAN Connector			X
Front Panel (FP1 + FP2)	Result		
	Pass	Fail	N/A
Power On Button	X		
IDE LED			X
External Buzzer			X
On Board Buzzer			X
Power LED			X
Reset Switch			X
Keyboard Lock			X
Jumpers Function	Result		
	Pass	Fail	N/A
ATX simulates AT			X
Audio Out Selection (W/O & W/ Amplifier)			X
LCD Power Select			X
COM1-Ring/5V/12V Selection			X
COM2-Ring/5V/12V Selection			X
COM2 RS-232/422/485 Selection (Depends on BIOS)			X
COM3-Ring/5V/12V Selection			X
COM4-Ring/5V/12V Selection			X
Clear CMOS			X
Touch Screen Operating Mode Selection			X
Clock Shift of TFT LCD			X
Power Connector & Function	Result		
	Pass	Fail	N/A
DC Power Connector	X		
ATX 24 Pin Power Connector			X
ATX Power Connector			X
ATX Power_12V Connector			X

AT Power Connector				X
Big 4P Power Connector				X
Mini 4P Power Connector				X
External Power Connector(-12/-5V)				X
Option ATX Power Connector (PS-ON / +5VSB)				X
LAN Connector & Function		Result		
		Pass	Fail	N/A
LAN Speed LED	LAN1			X
	LAN2			X
LAN Active LED	LAN1			X
	LAN2			X
LAN Link LED	LAN1			X
	LAN2			X
LAN 10/100 Ethernet		X		
LAN 1G Ethernet				X
PCI Connector & Function		Result		
		Pass	Fail	N/A
Mini PCI Slots				X
PCI Slots				X
PCI Express				X

## 2. Power Connector Test (110V / 220V )

Test Method	Result		
	Pass	Fail	N/A
DC Power Connector- Power On/Off for 10 times in DOS	X		
ATX Connector - Power On/Off for 10 times in DOS			X
AT Connector - Power On/Off for 10 times in DOS			X
5V Only - Power On/Off for 10 times in DOS			X

## 3. Timer Accuracy Test

System Clock & RTC Clock Test				
Test Method	Margin for error	Result		
		Pass	Fail	N/A
System Clock in Power On Mode	±1 second during 24 hours	X		
RTC Clock in Power On Mode	±1 second during 24 hours	X		
RTC Clock in Power Off Mode	±1 second during 24 hours	X		
Watchdog Timer Test		Result		
		Pass	Fail	N/A
Time-out Interval	10 sec	X		
	60 sec	X		
	255 sec	X		

## 4. Network HUB / LAN Connection Test

Location		LED Type				Result		
						Pass	Fail	N/A
LAN1 LED		Active LED						X
		Link LED						X
		Speed LED						X
LAN2 LED		Active LED						X
		Link LED						X
		Speed LED						X
Location	Speed	HUB Type	Cable Length	HUB Speed	Onboard LAN Speed	Result		
						Pass	Fail	N/A
Onboard LAN1	10/100/1000 Mbps	HP J4095A 24 Ports	100M	100 MBps	100	X		
		D-Link DGS-1008T	100M	1GBps	100	X		
		D-Link DES-1316 PoE Switch	100M	100 MBps	100	X		
		Intel InBusiness 8 Port	100M	100 MBps	100	X		
		Accton DeskTop-3005	100M	100 MBps	100	X		
		SVEC FD916H (10 Mbps HUB)	100M	10 MBps	10	X		

## 5. Hardware Compatibility

CPU Compatible Test							
CPU Type	FSB	Prime95 Version	Result				
			Pass	Fail	N/A		
Intel Celeron M processor 1.5GHz	400	V2414	X				
Memory Compatibility Test							
Memory Brand	Memory Chipset	Frequency	Size	MemTest86 Version	Result		
					Pass	Fail	N/A
Apacer	PC3200 DDR 266	266	1G	V1.70	X		
Audio Basic Function Test					Result		
					Pass	Fail	N/A
System Sound							X
CD_In							X
CD_In Sound Recorder							X
Play Sound Recorder							X
Line Out							X
Line In							X
Line In Sound Record							X
MIC Speaker				Dynamic			X
				Condenser			X
MIC Sound Recorder				Dynamic			X
				Condenser			X
Audio 5.1 Channel with S/P DIF Function Test					Result		
					Pass	Fail	N/A
2-channel mode for stereo speaker output							X
4-channel mode for 4 speaker output							X
6-channel mode for 5.1 speaker output							X
S/P DIF function Test				Input			X
				Output			X
On Board TV Function Test					Result		
					Pass	Fail	N/A
NTSC		AV Terminal					X
PAL							X
NTSC		S Terminal					X
PAL							X
On Board LCD Function Test							



TFT LCD	Type	Voltage	Result		
			Pass	Fail	N/A
LVDS	Sharp LQ12S1LG61 /12"/800*600	3.3V	X		
	AUO G065VN01 V.0 / 6.5" / 640x480 / 18bit (4:3)	3.3V			X
	AUO G065VN01 V.0 / 6.5" / 640x480 / 24bit (4:3)	3.3V			X
	AU B104SN02 / 10.4" / 800*600 / 18bit (4:3)	3.3V			X
	AU G150XG01 V.0 / 15" / 1024*768 / 18bit (4:3)	3.3V			X
	AU M150XN07 V.2 / 15" / 1024x768 / 24bit (4:3)	3.3V			X
	AU M170EG01 / 17" / 1280*1024 / 48bit (4:3)	5V			X
	AU M170XW01 V.1 / 17" / 1280x768 / 24bit (16:9)	5V			X
	AUO T260XW02 / 26" / 1366x768 / 24bit	5V			X
	AU M201UN02 V.5 / 20.1" / 1600x1200x48bit	5V			X
	AUO T370HW01 / 37" / 1920x1080 / 48bit	26V			X
TTL	Toshiba LTM10C209A / 10.4" / 640*480 / 18bit (4:3)	5V			X
	NEC NL8060AC31-12 / 12.1" / 800*600 / 18bit (4:3)	3.3/5V			X
	Sharp LQ121S1DG11 / 12.1" / 800*600 / 18bit (4:3)	3.3V			X
	LG LM151X2-C2TH / 15.1" / 1024x768 / 18bit (4:3)	3.3V			X
	Fujitsu FLC38XGC6V-06 / 15" / 1024*768 / 36bit (4:3)	5V			X

**PCI Slot Function (PCI Adapter Card) Test**

Model	Type	Result		
		Pass	Fail	N/A
CHAINTECH NVIDIA GeForce4 MX440-8X	VGA Card			X
SC3000 CMI8738/C3DX	Sound Card			X
Takram DC-395U V1.02	SCSI Card			X
I-VIEW CP-1400AS (with Age STD-477FAI CCD)	Capture Card			X
Intel GD82559 10/100 Mbps Fast Ethernet Adapter	LAN Card			X
D-Link DWL-520+ Wireless LAN	LAN Card			X
ADAPTEC 1420SA RoHS 4-Port SATA II RAID	RAID Card			X
LEMEL MD V1456VQH-P2 PCI MODEM Card	Modem Card			X
D-Link DU-520 USB 2.0	USB Hub Card			X
Tekram TR-822 Serial ATA 150 [SA-001] + SATA HDD Seagate ST3120026AS 120GB	SATA Card			X

**ISA Slot Function Test**

	Result		
	Pass	Fail	N/A
Creative CT4170 Sound Blaster Sound Card			X
Adaptec AHA-1510/20/22B SCSI Card			X

**PCI-Express Function Test**

Model	Result		
	Pass	Fail	N/A
SUNIX SATA1414 VER 1.1 PCI-Express x1 SATA Card			X
SksKonnnect SK-9E21D 10/100/1000 Base-T Adapter PCI-Express x1 LAN Card			X
Adaptec AAR-1430SA SATAII HostRAID Controllers PCI-Express x4 RAID Card			X
ASUS EAX1600PRO/TD/256M/A (ATI Chipset) PCI-Express x16 VGA Card			X
WinFast PX6200 TC TDH PCI-Express x16 VGA Card			X

<b>HDD Compatibility Test</b>			
Model	Result		
	Pass	Fail	N/A
FUJITSU MHV2040AC IDE 40G	X		
<b>CD/DVD-ROM Compatibility Test</b>			
Model	Result		
	Pass	Fail	N/A
LITE-ON LITEON DX-20A4PU (USB DVD-ROM)	X		
<b>IDE Cable Function test</b>			
IDE Model	Result		
	Pass	Fail	N/A
40 Pin Cable ATA66			X
44 Pin Cable ATA33	X		
80 Pin Cable ATA100			X
<b>USB Function Test</b>			
USB Basic Function Test	Result		
	Pass	Fail	N/A
USB Controller	X		
USB 2.0 Controller	X		
USB Keyboard Support	X		
USB Mouse Support	X		
USB 1.1 Compatible Test	Result		
	Pass	Fail	N/A
USB 1.1 Compatible Test	X		
USB 2.0 Compatible Test	Result		
	Pass	Fail	N/A
USB 2.0 Compatible Test	X		
USB 2.0 Function Test	Result		
	Pass	Fail	N/A
Install Windows XP Professional from HighSpeed Device: USB2.0 DRW-1604P-D/WHT/G/ASUS	X		
USB Device Full Loading Test	Result		
	Pass	Fail	N/A
Mitsumi FLL3.5 D353GUE/FUE	X		
USB HDD 20GB	X		
USB Card Reader			X
USB Mouse	X		
USB Thumb drive Sandisk 1G	X		
Floppy Disk Controller Function Test	Result		

		Pass	Fail	N/A	
Copy and compare file between C: and A / B:				X	
Change Floppy to None value				X	
Swap FDD				X	
<b>Peripheral Compatibility-Storage Device</b>					
Model	Interface	Result			
		Pass	Fail	N/A	
FUJITSU MCB3064SS	SCSI			X	
IOMega ZIP 100 parallel port	Parallel			X	
IOMega ZIP100MB Internal ATAPI Drive	IDE			X	
DOC				X	
Type-I CF	Fix / PIO Mode			X	
Type-I CF	Fix / UDMA Mode			X	
<b>Digital I/O Connector Test</b>		Result			
		Pass	Fail	N/A	
Input Address:				X	
Output Address:				X	
VCC: (5V)				X	
DIO-1 Function Test				X	
DIO-2 Function Test				X	
<b>Adapter Compatibility- Industry Control Card PC/104, PC/104+, PCI-104 Modules</b>					
Interface	Model	Type	Result		
			Pass	Fail	N/A
PC/104	AAEON PCM-5600	Modem Module			X
	AAEON PCM-3115B	PCMCIA Module			X
PC/104+	AAEON PCM-3430	SCSI Module			X
PCI-104	AAEON PCM-FA00	Mini-PCI Converter			X
	AAEON PCM-3794	SCSI Module			X
	AAEON PCM-3730	Intel 82559 LAN Module			X
<b>On-Board RAID Function Test</b>					
Model	Interface	Result			
		Pass	Fail	N/A	
Set SATA HDDs as RAID 0	SATA			X	
Set SATA HDDs as RAID 1	SATA			X	
Set SATA HDDs as RAID 10	SATA			X	
Set SATA HDDs as RAID 5	SATA			X	
<b>COM Function Test</b>		Result			
		Pass	Fail	N/A	
COM Port Burn In Test overnight		X			
<b>Disk On Module [DOM] Compatibility Test</b>					
Model	Interface	Result			
		Pass	Fail	N/A	

Transcend / TS512MDOM40V / 512MB	IDE 40 Pin			X
Transcend / TS512MDOM44V / 512MB	IDE 44 Pin			X
<b>Mini PCI Card Compatibility Test</b>				
Model (Use PCI-104 transform board: MBC-1TM Rev.A1.0)	Interface	Result		
		Pass	Fail	N/A
GM-100 WLAN 11g Mini PCI Card (Model: Sky Thru GC-100)	LAN			X
GM-101 WLAN 11b/g 54Mbps Mini PCI Card (Model: VNT6655AM)	LAN			X
PER-C20S SATA RAID MiniPCI Card (Silicon Image Sil3512ECTU128 QF7227.1-1)	SATA			X
<b>COM/LPT Ports &amp; RS-232/422/485 Function Test</b>		Result		
		Pass	Fail	N/A
RS-422 for COM2		X		
RS-485 for COM2		X		
COM1		X		
COM2		X		
LPT1				X
LPT2				X
<b>Card Bus(PCMCIA) Compatibility Function Test</b>				
Model	Result			
	Pass	Fail	N/A	
Intel PRO/Wireless 2011B LAN PC Card (WPC2011BWW)			X	
PQI 16MB Compact Flash Adapter (64MB PQI CF Card inserting)			X	
Kingston datapack DP-PCM2 / 2GB (PC Card TypeII HDD)			X	
PCi GW-NS54SG Cardbus Adapter Wireless LAN Type-II			X	

## 6. O.S. Compatibility Test

Installation Operation System Compatibility Test			Result		
			Pass	Fail	N/A
[ ] Linux-RedHat 9.0 or [ ] Fedora Core 4.0 [ ] Fedora Core 7.0					X
Windows Server 2003 English Version / Standard Edition 5.2.3790					X
Windows Server 2003 English Version /Standard x64 Edition					X
Windows XP Professional English Version V2002 Service Pack 3			X		
Windows XP Professional English Version /Standard x64 Edition					X
Windows 2000 Professional English Version V5.00.2195 Service Pack4			X		
Windows Server 2000 English Version					X
Windows 98SE English Version V4.10.2222A					X
DOS 6.22 English Version					X
Utility and Driver Test					
OS	Drivers Version		Result		
			Pass	Fail	N/A
Linux-Red-Hat 9.0 / Kernel 2.4.20-8	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X
	Audio Driver	N/A			X
Windows Server 2003 English Version Standard Edition 5.2.3790	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X
	Audio Driver	N/A			X
Windows Server 2003 English Version Standard x64 Edition	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X
	Audio Driver	N/A			X
Windows XP Professional English Version V2002 Service Pack 2	Chipset Software	6.0.1.1002	X		
	Graphics Media	6.14.10.4020	X		
	LAN Driver	7.1.2.0	X		
	Audio Driver	5.10.0.5630	X		
Windows XP Professional x64 Edition English Version Service Pack 2 V2002	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X
	Audio Driver	N/A			X
Windows 2000 Professional English Version V5.00.2195 Service Pack 4	Chipset Software	6.0.1.1002	X		
	Graphics Media	6.14.10.4020	X		
	LAN Driver	7.1.2.0	X		
	Audio Driver	5.10.0.5630	X		
Windows Server 2000 English Version	Chipset Software	N/A			X
	Graphics Media	N/A			X
	LAN Driver	N/A			X
	Audio Driver	N/A			X
Windows 98SE English Version	Chipset Software				X
	Graphics Media				X

V4.10.2222A	LAN Driver				X
	Audio Driver				X

## 7. BIOS Function Test

Test Item	Result		
	Pass	Fail	N/A
Memory Beep Test			X
Standard CMOS Setup Test	X		
Boot Sequence Test	X		
<b>Power Management Test</b>			
APM Power Management Test	X		
ACPI Power Management Test	X		
Power On Function Test			X
Wake Up Event Test	X		
Power On after Power Failure Test	X		
CMOS Backup / Clear CMOS Test	X		
Boot ROM Test (RPL/PXE)	X		
Supervisor / User Password Test	X		
CRT / LCD / TV Function Test	X		
TV Standard Function Test			X
Init Display First Function Test	X		
On-Chip Serial ATA Function Test			X
SATA Mode-IDE/RAID Function Test			X
<b>PC Health Status</b>			
Voltage Monitor Test	X		
FAN Speed Monitor Test			X
Temperature Monitor Test	X		
Swap Floppy Drive & Boot up Floppy Seek Function Test			X
USB Onboard Device Function Test	X		
COM Address / IRQ Test	X		
LPT Address / IRQ Test			X
BIOS AWDFLASH Program Test	X		

## 8. Performance Test

### Platform Information

PCB Model	FOX-120
BIOS	FOX-120 BIOS Rev 1.0 (7/7/2008)
Operating System	Windows XP Professional V2002 Service Pack 3
CPU	Intel Celeron M processor 1.5GHz
Memory	Apacer PC3200 DDR 266 1GHz
SATA HDD	N/A
Primary IDE Master	FUJITSU MHV2040AC IDE 40G
Primary IDE Slave	N/A
CRT	N/A
LCD	Sharp 12" LQ121S1LG61
Compact Flash	N/A
Backplane	N/A
Riser Card	N/A
Chipset Software	Intel Chipset software Installation Utility--6.0.1.1002--2004/03/07
Graphics Media	Intel 82852/82855 GM/GME Graphics controller--6.14.10.4020--2005/01/23
LAN Driver	Intel PRO10/100 VE Network connection--7.1.2.0--2004/02/10
Audio Driver	Realtek AC'97 Semiconductor Corp--5.10.0.5630--2004/07/01
Touchscreen Driver	Touchscreen Controller—4.3.7.3203—2006/08/03
Power Supply	SINPRO MPU100-108 9V~30V DC

### Test result:

Final Reality V1.01—BenchMark Test (Reality Marks)		
2D Image	19.89	
3D	6.29	
Bus transfer	25.33	
Overall	13.23	Reality marks
3Dmark2001SE Pro (Demo version)		
3DMark2001SE Build 330_Benchmark mode	1303	
PCMark2002		
CPU	5001	
Memory	3455	
HDD	576	
PCMark05		
PCMark	N/A	
CPU	2350	
Memory	1721	
Graphics	N/A	
HDD	2284	