Report NO: 17I010002

## PER-C40L

# INTEL ® 82580EB/i350-AM4 PCI-Express 1GbE SFP/Copper 4Port Module

## Compatibility Test Report

Summary Pass  Fail Pass with Deviation (Comment:)								
Test Results Category								
	Critical	Major	Minor	Enhancement				
Defect Found	0	0	0	0				
Defect Unsolved	0	0	0	0				

Issue date	QE Manager	Test Engineer
2017-01-19	KJ Wang	Max Chang

## **Specification Validation Main Specification**

Item	Specification		Result		Note
Item	Opecification	Pass	Fail	N/A	Note
Product Name	PER-C40L				
Form Factor	1G LAN Module				
Main Chipset	1 x INTEL® 82580EB Ethernet				
Bypass	W/O BYPASS				
Host Interface	PCI Express [x4]				
LAN Port	SFP 1GbE Connector x 4				
Indicator	4 x LED for Active/Link				
Qualification	CE/FCC Class A				
Operation Temp.	0°℃~40°ℂ	$\boxtimes$			
Dimension	137.8 (L) x 88 (W) mm	$\boxtimes$			

O.S. Support

Item	Specification	Result			Note
Item	Specification		Fail	N/A	NOTE
DOS(graphic and tex	ture mode)	$\boxtimes$			
Microsoft Windows	Windows 7 64 bit	$\boxtimes$			
Linux	Linux Kernel 2.6.X	$\boxtimes$			

### **Platform Information**

i lationni information						
Device Information	Note					
NED						
FWS-7400						
FWB-7400 A1.0						
FWS-7400 R1.1 (V0186M11) (07/22/2016)						
\\172.16.1.21\SAP-Beta\Products\PER-C40L\20160504						
Intel® Core™ i7-4770S (8M Cache, 3.90 GHz)						
Transcend DDR3 8GB 1333 SEC 207 HYKO K4B4G0846B						
Innodisk SSD 3MG2-P 64GB						
Pioneer 8X (DVR-XD11T)						
Philips 244E2SB/96 24"						
PER-T281 A0.1						
PER-C40L A1.0						
English Ubuntu16.04 Kernel 4.4.0-21-generic x86_64						
CentOS7 kernel: 3.10.0-229.11.1e17.x86_64						
☐ Windows 7 Ultimate 64Bit						
ATX Power Supply : FSP250-50LC 250W						
AT Power Supply: N/A						
DC Adapter : N/A						
N/A						
Chipset Information						
INTEL® 82580EB Ethernet Controller						
	NSD					

## **Summary Table of contents:**

1. Basic Function Test	4
1.1. LED / LCM / Button Function Test	4
1.2. Bypass Function Test	5
1.3. Gigabit Ethernet Function Test	6
1.4. Transceiver Compatibility Test	
2. O.S Compatibility Test	
2.1. Linux OS Compatibility Test	7
2.2. Windows OS Compatibility Test	8
3. LAN Performance Test	
3.1 DUT and Test Equipments	9
3.2 RFC-2544 performance test (2 port)	
3.3 RFC-2544 performance test (4 port)	11

## 1. Basic Function Test

#### 1.1. LED / LCM / Button Function Test

#### Procedure:

- Step1. To check Ethernet LED status can follow below methods.
  - A. Use LAN cable to connect 40Gbps Host PC, transmit some packets between Host PC and DUT.
  - B. Use LAN cable to connect 10Gbps Host PC, transmit some packets between Host PC and DUT.
  - C.Use LAN cable to connect 1000Mbps switch between Server PC and DUT, transmit some packets between Server PC and DUT.
  - D.Use LAN cable to connect 100Mbps switch between Server PC and DUT, transmit some packets between Server PC and DUT.
  - E. Use LAN cable to connect 10Mbps switch between Server PC and DUT, transmit some packets between Server PC and DUT.

	Speed LED
40G bps	Color blue
10G bps	Color blue
1000Mbps	Color orange
100Mbps	Color green
10Mbps	Color blank

	Link/Act LED
Transmit	Yellow LED Blink

#### Result:

NI-	To at it and	Result			Damada
No.	Test item	Pass	Fail	N/A	Remark
1	40G connection LAN LED action as below: Speed LED: Blue Link LED: Yellow / Blinking				
2	10G connection LAN LED action as below: Speed LED: Blue Link LED: Yellow / Blinking				
3	1G connection LAN LED action as below: Speed LED: Orange Link LED: Yellow / Blinking				
4	100M connection LAN LED action as below: Speed LED: Blue Link LED: Green / Blinking				
5	10M connection LAN LED action as below: Speed LED: Blue Link LED: Blank / Blinking				

	PER-C40L	Compatibility	Test Report

## 1.2. Bypass Function Test

(X) No Support

#### Procedure:

- Step1. Under Linux, execute AAEON SDK(LanByPass) to test Bypass function under power on and power off mode.
- Step2. SDK set "power on" is "PassTru and "power off" is "ByPass, and remove the AC power code. (G3 status)
- Step3. BIOS set power on is "PassTru" and power off is "Bypass", boot up system from G3 status..
- Step4. SDK set "power on" is "PassTru" and "WDT-ByPass", execute watch Dog.

#### Test result:

No	To at itam	Dower	Dower off	Result			Damada
No.	Test item	Power on Power off		Pass	Fail	N/A	Remark
	PassTru / ByPass	Bypass	Bypass			$\boxtimes$	
1	should work	Bypass	PassTru			$\boxtimes$	
ı	properly by SDK	PasTru	Bypass			$\boxtimes$	
	control.	PassTru	PassTru			$\boxtimes$	
2	LAN should switch to ByPass mode when system AC loss.( G3 status)	PassTru	ByPass				
3	Boot up from G3, LAN should switch to PassTru.	PassTru	ByPass				
4	WDT ByPass should	work properl	y.			$\boxtimes$	

#### 1.3. Gigabit Ethernet Function Test

Configuration:

1G switch: D-Link DGS-1210-16 100M switch D-Link DES-1008A 10M HUB SVEC FD916H

100 meters CAT6 cable

#### Procedure:

Step1. Each LAN port connect DHCP server.

Step2. Connect internet and ping Google (8.8.8.8).

Step3. Each LAN port connect host PXE PC and DUT BIOS enable PXE function.

Step4. BIOS select boot from LAN.

Step5. Test each LAN port WOL function properly which from OS shutdown and Dos power off.

Step6. Client PC to install and execute iperf and host PC execute iperf –s (Windows OS)

Step7. Iperf test with 1G, 100M, 10M switch/Hub.

<#yum install iperf>

<#iperf -c 192.168.3.58 -w 100M -t 60 -i 1>

#### Test result:

Test item			Result		Note
restitem		Pass	Fail	N/A	Note
Internet Browser (DHCP Server) Ping website(8.8.8.8) should work properly	All LAN	$\boxtimes$			
LAN Boot (PXE) Boot from LAN should work properly				$\boxtimes$	
Wake On LAN WOL should work properly when resume from S5/Dos off	All LAN			$\boxtimes$	
1Gbps connection lperf test result should not loss and max bandwidth must be in 900MB or more.	All LAN	$\boxtimes$			Test max bandwidth: 900MB/s
100Mbps connection lperf test result should not loss and max bandwidth must be in 90MB or more.	All LAN			$\boxtimes$	Test max bandwidth: MB/s
10Mbps connection lperf test result should not loss and max bandwidth must be in 9MB or more.	All LAN			$\boxtimes$	Test max bandwidth: MB/s

## 1.4. Transceiver Compatibility Test

Procedure:

Connect transceiver and check if it works properly.

#### Test result:

Transceiver Test			Result		Note	
IIai	isceiver rest	Pass	Fail	N/A	Note	
1G	SX Volktek GBM-104 1.26Gbps					
1G	SX Axcen AXGE-5854-0511 SFP-1000SX					

## 2. O.S Compatibility Test

### 2.1. Linux OS Compatibility Test

#### Procedure:

- Step1. Install Linux x86 or x64 OS from USB DVD ROM.
- Step2. Enter command "Ispci" to check if devices were detected.
- Step3. Install LAN driver to system.
- Step4. Execute the following command to test driver and verify

Step 4.1 Driver install

- (1) Checked whether the command "Insmod drivername" can function normally, or not.
- (2) Checked whether the command "rmmod drivername" can successful uninstall the driver, or not

Step 4.3 ifconfig Ethernet

- (1) Execute command "ifconfig ethx down" close Ethernet.
- (2) Execute command "ifconfig ethx up" start Ethernet.

Step 4.6 Jumbo Frame

Setting #ifconfig LAN mtu 9000

Check #ifconfig LAN (mtu will change from 1500 to 9000)

Step 5 Ping Google or Host PC.

#ping 8.8.8.8 or #ping 192.168.xx.xx -s 65500 -c 100.

#### Test result:

2.1.1 English Ubuntu16.04 Kernel 4.4.0-21-generic x86\_64

Test Item			Result		Note
rest item		Pass Fail N/A			Note
System s	hould not any error during installation process.	$\boxtimes$			
Ispci to ch	neck LAN devices.				
System s	hould not error during LAN driver installation.				
"Insmod	drivername" should install driver normally.	ly. 🛛 🗆			
"rmmod	drivername" should uninstall driver normally.	/. 🛛 🔲 🖂			
Ifoonfia	Ethernet interface should be closed when execute command ""ifconfig ethx down"	$\boxtimes$			
Ifconfig	Ethernet interface should be started when execute command "ifconfig ethx up"	$\boxtimes$			
Jumbo Jumbo function should work properly		$\boxtimes$			
Ping test Ping should work normal.					

#### 2.1.2 CentOS7 kernel: 3.10.0-229.11.1e17.x86\_64

Test Item		Result		Note	
rest item	Pass	Fail	N/A	Note	
System should not any error during install process.	$\boxtimes$				
Ispci to check LAN devices.	$\boxtimes$				
System should not error during LAN driver installation.					
"Insmod drivername" should install driver normally.					
"rmmod drivername" should uninstall driver normall	/.				
Ifconfig Ethernet interface should be closed when execute command ""ifconfig ethx down"	$\boxtimes$			CentOS support ifup/ifdown	

			PER-C40L Compatibility Test Repo					
	Ethernet interface should be started when execute command ""ifconfig ethx up"	$\boxtimes$						
Jumbo	Jumbo function should work properly	$\boxtimes$						
Ping test	Ping should work normal.	$\boxtimes$						

## 2.2. Windows OS Compatibility Test

#### Procedure:

- Step1. Install Windows OS from USB DVD ROM.
- Step2. Install all required driver to system.
- Step3. Connect internet, check each LAN port function.
- Step4. Insert USB flash, check each USB port function.
- Step5. ACPI S5 and reset function test.
- Step6. ACPI S3 and S4 function test if support graphics driver.

#### Test result:

2.2.1 Windows 7 Ultimate 64bit English version

Test Item				Result		Note
Pass Fail I					N/A	Note
System should not any error during install process.						
All requir	All required driver should be installed.					
	ed internet and ping ite should work 8.8.8.8)	NIM module: port 1~4	$\boxtimes$			
USB ports should work properly.			$\boxtimes$			
Shutdow	System should be shutdown when click "shutdown" icon		$\boxtimes$			
Reboot	System should be reset when click "Reset" icon.		$\boxtimes$			
S3	System should be sleep when click "Sleep" icon and resume function should work properly		$\boxtimes$			
S4	1 -	sleep when click "Sleep" unction should work properly.	$\boxtimes$			

## 3. LAN Performance Test

## 3.1 DUT and Test Equipments

#### 3.1.1. DUT Specification

#### Hardware:

➤ Model name: <u>FWS-7400</u>

➤ M/B: <u>FWB-7400 A1.0</u>

➤ CPU: Intel® Core TM i7-4770S (8M Cache, 3.90 GHz)

RAM: Transcend DDR3 8GB 1333 SEC 207 HYKO K4B4G0846B

HDD: Innodisk SSD 3MG2-P 64GB

NIM module: PER-C40L A1.0

#### Software:

► BIOS: <u>FWS-7400 R1.1 (V0186M11) (07/22/2016)</u>

Operating System: <u>CentOS5.6 Kernel 2.6.18-238.el5PAE</u>

NIM LAN driver: <u>igb-5.3.5.3.tar</u>

#### 3.1.2. Test Equipments Specification

#### SPIRENT Smartbits

Chassis: SPIRENT Smartbits 600B

Chassis Version: 2.80.003 (Cur) 2.50.000

Chassis Serial #: 06014047

➤ Library: <u>6.00-29</u>

> API: <u>5.50.42.01</u>

File: <u>0550042</u>

Module: 2 \* LAN-3324A SmartMetrics XD 4-Port 10/100/1000Base-T Gigabit Ethernet


> Test Software: <u>SmartFlow5.50.42.1</u>

## 3.2 RFC-2544 performance test (2 port)

#### 3.2.1. Throughput test (2 port)

#### **Test Description:**

- In DUT System, set routing function enabled.
   # echo 1 > /proc/sys/net/ip\_forward>
- 2. Test Configuration as below Figure.



- 3. Smartflow\Test Group to add port1<->port2 with Bi-directional,
- 4. The tester set loading traffic from 1% to 100% and the traffic step is 50%.
- 5. Interaction Constants Duration Time Set to 60 Sec.
- 6. Test all LAN ports performance.

#### **Test Result:**

Test Group: <LAN1-LAN2 bi-directional>
Test Group: < LAN3-LAN4 bi-directional >


Speed: 1000_Full	Frame Size(bytes)									
LAN ports	64 128 256 512 1024 1280 15 <sup>2</sup>									
1-2	97.67	100	100	100	100	100	100			
3-4	97.67	100	100	100	100	100	100			

### 3.3 RFC-2544 performance test (4 port)

#### 3.3.1. Throughput test

#### **Test Description:**

- In DUT System, set routing function enabled.
   <# echo 1 > /proc/sys/net/ip\_forward>
- 2. Test Configuration as below Figure.



- 3. Smartflow\Test Group to add port1<->port2 with Bi-directional, port3<->port4 with Bi-directional.
- 4. The tester set loading traffic from 1% to 100% and the traffic step is 50%.
- 5. Interaction Constants Duration Time Set to 60 Sec.
- 6. Test all LAN ports performance.

#### **Test Result:**

Test Group: <LAN1-LAN2 bi-directional>; <LAN3-LAN4 bi-directional>

Speed: 1000_Full		Frame Size(bytes)								
LAN ports	64	128	256	512	1024	1280	1518			
NIM 1~4	84.53	100	100	100	100	100	100			