

ACP-1074

With mSATA

Supplier: POKI / Carton size: 340(L)*195(W)*250(H) mm

Package Drop Test Report

Report NO: 15P030042



Summary	<p><input checked="" type="checkbox"/> Pass</p> <p><input type="checkbox"/> Fail Note : There is/are ___ defect(s) not list in the report, please check it in the DTS Website.</p> <p><input type="checkbox"/> Pass with Deviation</p> <p>Comment: _____</p>
---------	--

Issue date

2015-12-25

Approval

KJ Wang

Test Engineer

Jerry Chen

Test item list

1. *Test item list* ----- 2
2. *Configuration of EUT* ----- 3
3. *Package drop test* ----- 4

Testing Result

Num	Test item list	Result	Remark
1	Package drop test	Pass	

Configuration of EUT

Num	Item	Spec
1.	System Name	ACP-1074 Ver. 0.1
2.	M/B Name	PBA-BT01 Ver. A1.0
3.	BIOS / Version	ACP-1074 R0.1 (C174AM01) (10/02/2015) x64
4.	CPU Type	Intel Celeron J1900 / 1.99 GHz
5.	Memory	Transcend / DDR3L 1600 SO I / 2GB * 1 / SEC K4B2G0846Q
6.	mSATA	Innodisk / mSATA mini 3ME3 32GB / DEMSM-32GD09SW1DC-26
7.	Test Software	Windows 7 / Run PassMark Burn In Test 7.1 Pro
8.	Adapter	FSP / FSP060-DBAB1

Photos

After Test



Package Drop Test

Test Date: 12-24-2015

Test Product: ACP-1074

Test Site: AAEON QE Dept.

Test Standard:

Reference ISTA PROJECT 1A

Test Equipment:

Drop Tester


KING DESIGN Co. LTD.

Model: KD-128A

Serial Number: UU110099190

Test Condition:

1. Test Phase: One corner. Three edges. Six face
2. Test Cycle: 1 Cycle
3. Test Height: 76cm
4. Test Weight: 1.7Kg
5. Sample Package: 1unit in single-package.
6. Test Drawing:



Test Result:

Packaging is not broken, main board no structure deformation and function was working normally after drop test.