



July 31, 2007

Mr. Morgan Lin
Aaeon Technology Inc
5th Fl, 135 Lane 235 Pao Chiao Rd, Hsin-Tien, Taipei, TW

Fax number: 886-2-8919-1049

E-mail: morganlin@aaeon.com.tw

Reference: File E241995 Project 07CA24741 Reference Report No. E241995-A12-UL-1

Product: UL/CUL FOR MEDICAL STATION, MODEL XXXXXONYX-175HTY-XX-XXXX & XXXXXONYX-195HTY-XX-XXXX

Dear Mr. Lin,

Any information and documentation involving UL Mark services are provided on behalf of Underwriters Laboratories Inc. (UL) or any authorized licensee of UL.

UL's investigation of your product has been completed under the above project number and the subject product was determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Classification Mark only at the factory under UL's Follow-Up Service Program to the subject product, which is constructed as described below:

Identical to MEDICAL STATION, MODEL XXXXXONYX-175HTY-XX-XXXX & XXXXXONYX-195HTY-XX-XXXX, which were submitted to UL for this investigation. The UL Records covering the product will be in the Follow-Up Services Procedure, File E241995, Volume X1, and Reference Report No. E241995-A12-UL-1.

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and all attached material to each manufacturing location as currently authorized in File E241995, Volume X1.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL's requirements and continued use of the UL Mark may be withdrawn.

Sincerely,

Jimmy Deng
Associate Project Engineer
Underwriters Laboratories Taiwan Co., Ltd.
E-mail: jimmy.deng@tw.ul.com

Reviewed by:

Thomas Huang
Project Engineer
Underwriters Laboratories Taiwan Co., Ltd.
E-mail: thomas.huang@tw.ul.com

Conga Chen
Engineer
Underwriters Laboratories Taiwan Co., Ltd.
Tel: 02-28967790
Fax: 02-28907443
E-mail: Conga.Chen@tw.ul.com

CC: Mr. Danny Lin
Prodigy Technology Consultant Co Ltd
Email: danny@prodigy-tech.com.tw
Fax: 886-2-2609-2399

NOTICE OF AUTHORIZATION TO APPLY THE UL MARK
This is to replace the previous letter dated October 12, 2007

October 17, 2007

Mr. Morgan Lin
Aaeon Technology Inc
5th Fl, 135 LANE 235 PAO CHIAO RD
Hsin-Tien, Taipei, Tw
E-mail: morganlin@aaeon.com.tw

Reference: File E241995 Project 07CA50621
Product(s): UL/CUL for Medical Station, Redefining Model Name

Dear Ms. Lin,

Any information and documentation involving UL Mark services are provided on behalf of Underwriters Laboratories Inc. (UL) or any authorized licensee of UL.

UL's investigation of your product has been completed under the above project number and the subject product was determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Listing Mark only at the factory under UL's Follow-Up Service Program to the subject product, which is constructed as described below:

Similar to products covered in the UL Follow-Up Services Procedure, File E241995, Volume X1.

- 1) Report Reference Number: E241995-A4-UL-1, Amendment 2, except for redefine models name from ONYX-173HTx-yz and ONYX-193HTx-yz to xxxxxONYX-173HTy-xxxxxxx and xxxxxONYX-193HTy-xxxxxxx, where x is 0-9, A-Z, "-" or blank; y is T or blank.
- 2) Report Reference Number: E241995-A5-UL-1, Amendment 2, except for redefine model name from ONYX-153HTx-yz to xxxxxONYX-153HTy-xxxxxxx, where x is 0-9, A-Z, "-" or blank; y is T or blank.
- 3) Report Reference Number: E241995-A12-UL-1, Amendment 1, except for redefine models name from xxxxxONYX-175HTy-xx-xxxx and xxxxxONYX-195HTy-xx-xxxx to xxxxxONYX-175HTy-xxxxxxx and xxxxxONYX-195HTy-xxxxxxx, where x is 0-9, A-Z, "-" or blank; y is T or blank.

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and all attached material to each manufacturing location as currently authorized in File E241995, Volume X1.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL's requirements and continued use of the UL Mark may be withdrawn.

Sincerely,

Jimmy Deng

Jimmy Deng
Associate Project Engineer
Underwriters Laboratories Taiwan Co., Ltd.
E-mail: jimmy.dneg@tw.ul.com

Shirley Cheng

Shirley Cheng
Conformity Assessment Specialist
Underwriters Laboratories Taiwan Co., Ltd.
Tel: (02)2896-7790
Fax: (02)2890-7443
E-mail: shirley.cheng@tw.ul.com

Reviewed by:

Samuel Wang

Samuel Wang
Section Manager
Underwriters Laboratories Taiwan Co., Ltd.
E-mail: samuel.wang@tw.ul.com

CC: Cerpass Technology Corp
E-mail: pennyt@cerpass.com.tw
Attn: Penny Tsai