



美商優力安全認證有限公司台灣分公司
UL International, L.L.C., Taiwan Branch
台北市 112 北投區大業路 260 號 1 樓
1st Fl 260 Da-Yeh Road Peitou Taipei City Taiwan 112
tel: 886-2-2896-7790 fax: 886-2-2891-7644
<http://www.ul.com.tw>

NOTICE OF AUTHORIZATION TO APPLY THE UL MARK

January 20, 2006
Aaeon Technology Inc.
5th Fl 135 Lane 235 Pao Chiao Rd Hsin-Tien
Taipei Taiwan

E-mail: morganlin@aaeon.com.tw
Reference: File E241995 Project 05CA56234 Report Reference Number: E241995-A4-UL-1, Amendment 1
Product(s): UL/C-UL Investigation for Medical Station: Additional a new Model that is ONYX-193HTx-yz, where x may be T or blank, y may be A-Z, and z may be 1 or 2.

Dear Mr. Lin,

Any information and documentation provided to you involving UL Mark services are provided on behalf of Underwriters Laboratories Inc.

UL's investigations of your products have been completed under the above project number and the subject products were determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow -Up Services Procedure and serves as authorization to apply the UL Classification Mark only at the factory under UL's Follow-Up Services Program to the subject products, which are constructed as described below:

Model ONYX-193HTx-yz is similar to Model ONYX-173HTx-yz, where x may be T or blank, y may be A-Z, and z may be 1 or 2 covered in the Follow -Up Services Procedure, File E241995, Volume X1, Report Reference Number: E241995-A4-UL-1, Amendment 1, except for the panel size.

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and all attached material to each manufacturing location as currently authorized in File E241995, Volume X1.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow -Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL's requirements and continued use of the UL Mark may be withdrawn.

Sincerely,

Jimmy Deng
Engineer
UL International, L.L.C., Taiwan Branch
E-mail: jimmy.deng@tw.ul.com

Reviewed by:

Thomas Huang
Associate Project Engineer
UL International, L.L.C., Taiwan Branch
E-mail: thomas.huang@tw.ul.com

Ted Tseng
Engineer
UL International, L.L.C., Taiwan Branch
Tel: 886-2-28907467
Fax: 886-2-28907443
E-mail: ted.tseng@tw.ul.com
CC: Attn: Ms. Sherry Lin

Cerpass Consultancy Corp.

E-mail: sherryl@cerpass.comtw

An independent organization working for a safer world with integrity, precision and knowledge.

