

<i>1. Test item list</i> -----	2
<i>2. Random Vibration Operation Test</i> -----	3
<i>3. Random Vibration Non-Operation Test</i> -----	4

Test Date: 07-02-2009

Test Product: DSS-5300

Test Site: AAEON QA Internal Lab.

Test Standard: Reference IEC68-2-64 Testing procedures

Test Fh: Vibration boardband random test

Test Equipment:

Vibration Simulator System

KING DESIGN Co. LTD.


Model: KD 9363-EM-600F2K-40N20

Serial Number: UU110099090

Date of Calibration: 10/16/2008

Test Condition:

1. Operation
2. Test Acceleration: 0.5Grms Random
3. Test Frequency: 5-500Hz
4. Test Axis: X, Y, Z axes
5. Test Time: 60min each axis
6. Test Software: Windows XP / Run one Microsoft media player simultaneously.
7. Test Vibration Curve:



Test Result:

No structure deformation was found, and function was working normally.

Test Date: 07-03-2008

Test Product: DSS-5300

Test Site: AAEON QA Internal Lab. -


Test Standard: Reference IEC68-2-64 Testing procedures
Test Fh : Vibration boardband random test

Test Equipment:

Vibration Simulator System
KING DESIGN Co. LTD.
Model: KD 9363-EM-600F2K-40N20
Serial Number: UU110099090
Date of Calibration: 10/16/2008

Test Condition:

1. Non - Operation
2. Test Acceleration: 1.5Grms Random
3. Test Frequency: 5-500Hz
4. Test Axis: X, Y, Z axis
5. Test Time: 60min each axis
6. Test Software: Windows 2000 / Run one Microsoft media player simultaneously.
7. Test Vibration Curve:



Test Result:

No problem was found after the random vibration non-operation test.