



美商優力安全認證有限公司台灣分公司  
UL International, L.L.C., Taiwan Branch  
台北市 112 北投區大業路 260 號 1 樓  
1st Fl 260 Da-Yeh Road Peitou Taipei City Taiwan 112  
tel: 886-2-2896-7790 fax: 886-2-2891-7644  
<http://www.ul.com.tw>

## NOTICE OF AUTHORIZATION TO APPLY THE UL MARK

January 26, 2006

TO : Aaeon Technology Inc.  
5th Fl 135 Lane 235 Pao Chiao Rd Hsin Tien  
Taipei Hsien Taiwan 231  
Attention: Mr. Morgan Lin  
Our Reference: File E231775 Project 06CA04282  
Product: Operator Panel, Model AOP-8120WT-XX employing the alternate source of DC/AC inverter, Hwa Youn Co., Ltd., type QF38V6.43, and add a new model AOP-8120HT-XX (X = 09, A-Z or blank) for UL/C-UL investigation.

Dear Mr. Lin,

Any information and documentation provided to you involving UL Mark services are provided on behalf of Underwriters Laboratories Inc.

UL's Investigation of your product has been completed under the above project number and the subject product was determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Recognized Marking and/or Recognized Component Mark only at the factory under UL's Follow-Up Services Program to the subject product which is constructed as described below:

Similar to products covered in the UL Follow-Up Services Procedure, File E231775, Volume X1, Report Reference No. E231775-A10-UL-1 Amendment1, except for employing the alternate source of DC/AC inverter and add a new model name.

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and all attached material to each manufacturing location as currently authorized in File E231775, Volume X1.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product is now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL's requirements and continued use of the UL Mark may be withdrawn.

Very truly yours,

**Tristan Wang**

Tristan Wang(Ext. 62116 )  
Engineer  
Conformity Assessment Services, 3013DTPI

CC: Cerpass Consultancy Corp.  
Email: [sherryl@cerpass.com.tw](mailto:sherryl@cerpass.com.tw)  
Attn: Ms. Sherry Lin

Reviewed by:

**Wisely Lin**

Wisely Lin(Ext. 62403 )  
Associate Project Engineer  
Conformity Assessment Services, 3013DTPI

An independent organization working for a safer world with integrity, precision and knowledge



**NOTICE OF AUTHORIZATION TO APPLY THE UL MARK**

2007-10-31

Page 1 of 2

MR. Morgan Lin  
Aaeon Technology Inc  
5th FL 135 Lane 235 Pao Chiao Rd  
Hsin-Tien, Taipei  
Taiwan

Fax number: 2-89191049  
E-mail: morganlin@aaeon.com.tw

Reference: File E231775 Project 07CA50218 P.O. Number 1330709079  
1. Embedded Control PC, Models xxxxxAEC-6810-xxxxxxx, xxxxxAEC-6820B-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation.  
2. Embedded Control PC, Models xxxxxAEC-6910-xxxxxxx, xxxxxONYX-6910-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation.  
3. Operator Panel, Models xxxxxAOP-8120HT-xxxxxxx, xxxxxAOP-8120WT-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation.  
4. 2U LAN Port Rackmount Firewall Platform, Models xxxxFWS-825xx-xxx-xxx-xxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation.  
Product: 5. Operator Panel, Models xxxxxAOP-8120DT-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation.  
6. Embedded Controller, Model xxxxxAEC-6920-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation.  
7. Embedded Controller, Model xxxxxAEC-6850-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation.  
8. Ethernet Operator Panel, Model xxxxxAOP-8070HT-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation.  
9. Operator Panel, Model xxxxxAOP-8150HT-xxxxxxx, xxxxxAOP-8150WT-xxxxxxx, Where x is 0-9, A-Z, "-" or Blank for UL/CUL Investigation.

Dear MR. Lin,

This letter replaced the previous letter dated October 30, 2007.

Any information and documentation involving UL Mark services are provided on behalf of Underwriters Laboratories Inc. (UL) or any authorized licensee of UL.

UL's investigation of your product has been completed under the above project number and the subject product was determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Listing Mark and/or Recognized Marking and/or Recognized Component Mark only at the factory under UL's Follow-Up Service Program to the subject product, which is constructed as described below:

- Similar to the subject model, which was submitted to UL for this investigation. The UL Records covering the product will be in the Follow-Up Services Procedure, File E231775, Volume X1, X2 and 2:
1. Report Reference No. E231775-A8-UL-1 Amendment 1, changing model names from "AEC-6810-XX and AEC-6820B-XX" to "xxxxxAEC-6810-xxxxxxx and xxxxxAEC-6820B-xxxxxxx".
  2. Report Reference No. E231775-A9-UL-1 Amendment 3, changing model names from "xxxxxAEC-6910-xx-xxxx and xxxxxONYX-6910-xx-xxxx" to "xxxxxAEC-6910-xxxxxxx, xxxxxONYX-6910-xxxxxxx".
  3. Report Reference No. E231775-A10-UL-1 Amendment 2, changing model names from "AOP-8120WT-XX, AOP-8120HT-XX" to "xxxxxAOP-8120HT-xxxxxxx and xxxxxAOP-8120WT-xxxxxxx".
  4. Report Reference No. E231775-A11-UL-2, changing model names from "FWS-825" to "xxxxFWS-825xx-xxx-xxx-xxx" and correcting Volume number to Vol. X2.

5. Report Reference No. E231775-A12-UL-1 Amendment 1, changing model names from "AOP-8120DT-XX" to "xxxxxAOP-8120DT-xxxxxx".
6. Report Reference No. E231775-A13-UL-1 Amendment 1, changing model name from "AEC-6920-XX" to "xxxxxAEC-6920-xxxxxx".
7. Report Reference No. E231775-A14-UL-1 Amendment 1, changing model name from "AEC-6850-Ax" to "xxxxxAEC-6850-xxxxxx".
8. Report Reference No. E231775-A17-UL-1 Amendment 1, changing model name from "xxxxxAOP-8070HT-xx-xxxx" to "xxxxxAOP-8070HT-xxxxxx".
9. Vol. 2, Sec. 1, changing model names from "AOP-8150HT-XX, AOP-8150WT-XX" to "xxxxxAOP-8150HT-xxxxxx, xxxxAOP-8150WT-xxxxxx".

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and a ll attached material to each manufacturing location as currently authorized in File E231775, Volume X1, X2 and 2.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL's requirements and continued use of the UL Mark may be withdrawn.

Sincerely,

**Joy Shen**

Joy Shen  
Project Handler  
Department: 3013DTAI

Reviewed by:

**Jay Hsu**

Jay Hsu  
Project Engineer  
Department: 3013DTAI

CC: Cerpass Technology Corp.  
Fax.: [pennyt@cerpass.com.tw](mailto:pennyt@cerpass.com.tw)  
Attn: Ms Penny Tsai