

**KING DESIGN INDUSTRIAL CO., LTD.**

4F, NO. 3, Lane 270, Pei Shen Road Sec. 3,

Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C

TEL: 886-2-2662-5100 FAX: 886-2-2662-3094

**VIBRATION TEST LABORATORY**<http://www.kdi.tw><http://www.vibration.com.tw>

E-mail:service@kdi.tw

**TESTING / INSPECTION REPORT**

REPORT NO : DT-150806-1

COMPANY : AAEON Technology Inc.

ADDRESS : 5F, No.135, Lane 235, Pao Chiao Rd.

Hsin-Tien City, Taipei, Taiwan, R. O. C.

TEL : 886-2-8919-1234

FAX : 886-2-8919-1049

SPECIMEN : RTC-600A




DATE OF RECEIVED : 2015/08/06

DATE OF TESTED : 2015/08/06

TEST / INSPECTION ITEMS : Drop Test

## REMARKS :

- The laboratory is accredited by ISO/IEC 17025 General Requirements for the Competence of Calibration and Testing Laboratory.
- The results only apply to the device under test.
- This report is 10 pages, and no part of it may be abstracted or reproduced.

Test Engineer : 	
Approval Signatory 2015.8.10 	Laboratory Head : 

金頓科

**KING DESIGN INDUSTRIAL CO., LTD.**

4F, NO. 3, Lane 270, Pei Shen Road Sec. 3,

Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C

TEL: 886-2-2662-5100 FAX: 886-2-2662-3094

**VIBRATION TEST LABORATORY**<http://www.kdi.tw><http://www.vibration.com.tw>

E-mail:service@kdi.tw

## TESTING / INSPECTION REPORT

### TESTING EQUIPMENT :

Drop Testing System : KING DESIGN KD-208, S/N : LAB001

### TEST ENVIRONMENT :

Temperature : 26°C (25±10°C)

Relative Humidity : 67 %RH (50±25% RH)

### SPECIMEN :

Model : RTC-600A

Quantity : 2 units

### TEST SPECIFICATION :

Drop Height : 150 cm

Drop Onto : 8 corners &amp; 12 edges &amp; 6 faces

Test Cycle : 1 cycle

### TEST RESULT :

Describe	PASS	FAIL	Non-Judgment
Function judgment <sup>(1)</sup>	√	---	---
Appearance check <sup>(2)</sup>	√	---	---

(1)—Booting function was normal after the test.  
(2)—No visible damages were found.



**KING DESIGN INDUSTRIAL CO., LTD.**

**VIBRATION TEST LABORATORY**


4F, NO. 3, Lane 270, Pei Shen Road Sec. 3,  
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C  
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094

<http://www.kdi.tw>  
<http://www.vibration.com.tw>  
E-mail: [service@kdi.tw](mailto:service@kdi.tw)

## TESTING / INSPECTION REPORT

### Testing photos

#### Drop height



**KING DESIGN INDUSTRIAL CO., LTD.**

4F, NO. 3, Lane 270, Pei Shen Road Sec. 3,


Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C

TEL: 886-2-2662-5100 FAX: 886-2-2662-3094

**VIBRATION TEST LABORATORY**
<http://www.kdi.tw>
<http://www.vibration.com.tw>

E-mail:service@kdi.tw


## TESTING / INSPECTION REPORT



Corner-1	C
Corner-2	F
Corner-3	D
Corner-4	E
Corner-5	B
Corner-6	G
Corner-7	A
Corner-8	H
Edge-1	CG
Edge-2	BF
Edge-3	DH
Edge-4	AE
Edge-5	CD
Edge-6	EF
Edge-7	AB
Edge-8	GH
Edge-9	AC
Edge-10	FH
Edge-11	BD
Edge-12	EG
Flat-1	CDGH
Flat-2	ABEF
Flat-3	ACEG
Flat-4	BDFH
Flat-5	EGFH
Flat-6	ABCD




**TESTING / INSPECTION REPORT**






TESTING / INSPECTION REPORT



15-11




## TESTING / INSPECTION REPORT





**TESTING / INSPECTION REPORT**






**KING DESIGN INDUSTRIAL CO., LTD.**

 4F, NO. 3, Lane 270, Pei Shen Road Sec. 3,  
 Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C  
 TEL: 886-2-2662-5100 FAX: 886-2-2662-3094

**VIBRATION TEST LABORATORY**
<http://www.kdi.tw>  
<http://www.vibration.com.tw>  
 E-mail:service@kdi.tw

## TESTING / INSPECTION REPORT






**KING DESIGN INDUSTRIAL CO., LTD.**

**VIBRATION TEST LABORATORY**

4F, NO. 3, Lane 270, Pei Shen Road Sec. 3,  
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C  
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094

<http://www.kdi.tw>  
<http://www.vibration.com.tw>  
E-mail:service@kdi.tw

## TESTING / INSPECTION REPORT



-END-