



# Test item list

---

1. *Test item list* ----- 2
2. *Configuration of EUT* ----- 3
3. *Package drop test* ----- 5

## Testing Result


| Num | Test item list    | Result | Remark |
|-----|-------------------|--------|--------|
| 1   | Package drop test | Pass   |        |

# Configuration of EUT

| Num | Item                      | Spec   |
|-----|---------------------------|--|
| 1.  | Model Name                | VPC-5600S / Ver. A0.2  |
| 2.  | Main Board                | VPC-5600S / Ver. A0.2  |
| 3.  | BIOS                      | VPC-5600 R0.7 (VP56AM07) (06/15/2017)  |
| 4.  | CPU                       | Intel Core i3-7100U 2.40 GHz   |
| 5.  | Chipset                   | Intel Kaby Lake SOC  |
| 6.  | Wide Temp. Memory         | innodisk 16GB DDR4 2400 W/T SODIMM * 2 / chipset: SEC K4A8G085WB   |
| 7.  | mSATA SSD & 2.5" SATA SSD | Transcend / mSATA / TS64GMSA370I / 64GB * 1 (for OS)<br>Transcend SSD420K / 256GB / TS256GSSD420K * 1 (for storage video file) |
| 8.  | Test Software             | Windows 10 / Run PassMark Burn In Test 8.1 Pro & EtroCenter Ver. 1,3,0,16  |
| 9.  | Camera                    | ETROVISION / EV8782Q-BD * 1  |
| 10. | POE Splitter              | Model No.: POS-1001 * 3  |

## Photos

### After Test





# Package Drop Test

**Test Date:** 11-02-2017

**Test Product:** VPC-5600S

**Test Site:** PO KI PAPER CONTAINER. ,LTD

**Test Standard:**

Reference ISTA PROJECT 1A

**Test Equipment:**

Drop Tester


KING DESIGN Co. LTD.

Model: KD-128A

Serial Number: UU110099185

**Test Condition:**

1. Test Phase: One corner. Three edges. Six face
2. Test Cycle: 1 Cycle
3. Test Height: 76cm
4. Test Weight: 4.9Kg
5. Sample Package: 1unit in single-package.
6. Test Drawing:



**Test Result:**

The packaging is not broken, main board no structure deformation and function was working normally after the drop test.