



Sealed Air Taiwan Ltd.

Taiwan Packaging Laboratory

No 20 Lane 238 Tun-Hwa N. Road, Taipei, Taiwan. Tel:(886)02-2713-5321 Fax:(886)02-2713-5334

**International Safe Transit Association
Certified Packaging Laboratory**



ID Number: ST-2304

Vibration Test Report

Test For: Astech Technology Co., Ltd.

Date Tested: Oct 6, 2000

Test Specimen: BK-100

Weight Of Product: 5.1 kgs

Cushion Material: Instapak Gflex

TEST METHOD: Fixed Displacement, Rotary Motion

Frist Part: 26.8 Minutes at 265 CPM = 7100 Number of Impacts

Rotation of 90 degree

Second Part: 26.8 Minutes at 265 CPM = 7100 Number of Impacts

Total : 14200 Number of Impacts

TEST RESULTS: After testing, the outer container still afforded reasonable protection to its contents. There was no apparent physical damage to the unit. Functional testing, however, was not performed.

CONCLUSION: Provided that this unit is found to be in good working order, this package is suitable for common parcel shipment of this product. It meets or exceeds the vibration test portion of the International Safe Transit Association Procedure 1A pre-shipment test specifications.

Please contact with me if you have any question!!

Mark Hsu
Packaging Lab manager/Packaging Designer
Tony Chang
Packaging Designer



Sealed Air Taiwan Ltd.

Taiwan Packaging Laboratory

No 20 Lane 238 Tun-Hwa N. Road, Taipei, Taiwan. Tel:(886)02-2713-5321 Fax:(886)02-2713-5334

**International Safe Transit Association
Certified Packaging Laboratory**



ID Number: ST-2304

Vibration Test Report

Test For: Astech Technology Co., Ltd.

Date Tested: Oct 6, 2000

Test Specimen: BK-100

Weight Of Product: 5.1 kgs

Cushion Material: Instapak Gflex

TEST METHOD: Fixed Displacement, Rotary Motion

Frist Part: 26.8 Minutes at 265 CPM = 7100 Number of Impacts

Rotation of 90 degree

Second Part: 26.8 Minutes at 265 CPM = 7100 Number of Impacts

Total : 14200 Number of Impacts

TEST RESULTS: After testing, the outer container still afforded reasonable protection to its contents. There was no apparent physical damage to the unit. Functional testing, however, was not performed.

CONCLUSION: Provided that this unit is found to be in good working order, this package is suitable for common parcel shipment of this product. It meets or exceeds the vibration test portion of the International Safe Transit Association Procedure 1A pre-shipment test specifications.

Please contact with me if you have any question!!

Mark Hsu
Packaging Lab manager/Packaging Designer
Tony Chang
Packaging Designer



Sealed Air Taiwan Ltd.

Taiwan Packaging Laboratory

No 20 Lane 238 Tun-Hwa N. Road, Taipei, Taiwan. Tel:(886)02-2713-5321 Fax:(886)02-2713-5334

**International Safe Transit Association
Certified Packaging Laboratory**



ID Number: ST-2304

Vibration Test Report

Test For: Astech Technology Co., Ltd.

Date Tested: Oct 6, 2000

Test Specimen: BK-100

Weight Of Product: 5.1 kgs

Cushion Material: Instapak Gflex

TEST METHOD: Fixed Displacement, Rotary Motion

Frist Part: 26.8 Minutes at 265 CPM = 7100 Number of Impacts

Rotation of 90 degree

Second Part: 26.8 Minutes at 265 CPM = 7100 Number of Impacts

Total : 14200 Number of Impacts

TEST RESULTS: After testing, the outer container still afforded reasonable protection to its contents. There was no apparent physical damage to the unit. Functional testing, however, was not performed.

CONCLUSION: Provided that this unit is found to be in good working order, this package is suitable for common parcel shipment of this product. It meets or exceeds the vibration test portion of the International Safe Transit Association Procedure 1A pre-shipment test specifications.

Please contact with me if you have any question!!

Mark Hsu
Packaging Lab manager/Packaging Designer
Tony Chang
Packaging Designer