



KING DESIGN INDUSTRIAL CO., LTD.  
5F, NO. 3, LANE 94, TSAO TI WEI, SHEN KENG  
HSIANG, TAIPEI HSIEN, TAIWAN, R.O.C.

Reliability & Communication Testing Instruments

http://www.instrument.com.tw  
E-mail: kingdsgn@ms8.hinet.net  
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094



## TESTING / INSPECTION REPORT

DATE : July 17, 2000  
REPORT NO : ST-000717-1

COMPANY : AAEON Technology Inc.  
5F, No.135, Lane 235, Pao Chiao Rd.  
Hsin-Tien City, Taipei, Taiwan, R. O. C.  
TEL:886-2-8919-1234  
FAX:886-2-8919-1049

SPECIMEN : Modular System Industrial Workstation with  
15" Flat-panel and Keyboard

TEST / INSPECTION ITEMS : Shock Test (See Page 2)

### REMARKS :

- The results only apply to the device under test.
- This report is 9 pages, and no part of it may be abstracted or reproduced.
- Attached pages are controlling pulse of shock test.

Test Engineer :	<i>Chiping</i>	
Approved by :	<i>Dave Lee</i>	Laboratory Head : <i>2000.7.18 Hung Ch...</i>





KING DESIGN INDUSTRIAL CO., LTD.  
5F, NO. 3, LANE 94, TSAO TI WEI, SHEN KENG  
HSIANG, TAIPEI HSIEN, TAIWAN, R.O.C.

Reliability & Communication Testing Instruments

http://www.instrument.com.tw  
E-mail: kingsgn@ms8.hinet.net  
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094



0424

## TESTING / INSPECTION REPORT

### TESTING EQUIPMENT :

- 1. Shock Testing System : (KD-DP-1200-60, S/N:KDS11054983)
- 2. Controller : (KD-1200-03C, S/N:KD674)
- 3. Accelerometer : (WR-732AT, S/N:871)

### TEST ENVIRONMENT :

- Temperature :  $20 \pm 2^{\circ}\text{C}$
- Humidity :  $70 \pm 20\% \text{ RH}$

### SPECIMEN :

- Model : AMB-2450
- Quantity : 1 piece

### SHOCK TEST SPECIFICATION :

- Wave Form : Half Sine wave
- Acceleration : 10 g
- Duration Time : 11 ms
- No. of Shock : Each axis 3 times
- Shock Direction : Bottom, Left, Top, Right, Front, Back axis

### TEST RESULT :

- Appearance check : No damage