



*Industrial Computing Platform Partner*

# ONYX-1722

With 2.5" HDD

## Shock Test Report

Report NO: 09P030067

Tester by: Terry Huang / 10/05/2009  
Engineer Date

Issued by: Rex Chang / 10/05/2009  
Engineer Date

Reviewed by: Wenyuan Yang / 10/05/2009  
Manager Date

<b>1. Test item list</b> -----	<b>2</b>
<b>2. Shock Operation Test</b> -----	<b>3</b>

**Test Date:** 10-03-2009

**Test Product:** ONYX-1722

**Test Site:** KING DESIGN Lab.


**Test Standard:** Reference IEC68-2-64 Testing procedures  
Test Fh: Vibration boardband random test

**Test Equipment:**

Vibration Simulator System  
KING DESIGN Co. LTD.  
Model: KD 9363EM-600F2K-50N120  
Serial Number: KDS11054986

**Test Condition:**

1. Operation
2. Test wave form: Half sine wave
3. Test Acceleration: 15G
4. Test Duration Time: 11ms
5. Test Axis:  $\pm X$ ,  $\pm Y$ ,  $\pm Z$  axis
6. Test Time: each axis 3 times
7. Test Software: Windows XP / Run one Microsoft media player simultaneously.
8. Test Shock Curve:



**Test Result:**

No structure deformation was found, and function was working normally.