



Industrial Computing Platform Partner

ONYX-192

With HDD

Vibration Test Report

Report NO: 09P030008

Issued by:	<u>Rex Chang</u> Engineer	/	<u>02/24/2009</u> Date
Reviewed by:	<u>Wenyuan Yang</u> Manager	/	<u>02/24/2009</u> Date

1. Test item list -----	2
2. Random Vibration Operation Test -----	3

Test Date: 02-24-2009

Test Product: ONYX-192

Test Site: AAEON QA Internal Lab.

Test Standard: Reference IEC68-2-64 Testing procedures

Test Fh: Vibration boardband random test

Test Equipment:

Vibration Simulator System

KING DESIGN Co. LTD.


Model: KD 9363-EM-600F2K-40N20

Serial Number: UU110099090

Date of Calibration: 10/16/2008

Test Condition:

1. Operation
2. Test Acceleration: 0.5 Grms Random
3. Test Frequency: 5-500Hz
4. Test Axis: X, Y, Z axes
5. Test Time: 60min each axis
6. Test Software: Windows XP / Run one Microsoft media player simultaneously.
7. Test Vibration Curve:



Test Result:

No structure deformation was found, and function was working normally.