



*Industrial Computing Platform Partner*

# **ONYX-2122**

With HDD

## **Vibration Test Report**

**Report NO: 09P030051**

Issued by:	<b>Rex Chang</b> _____ Engineer	/	<b>07/27/2009</b> _____ Date
Reviewed by:	<b>Wenyuan Yang</b> _____ Manager	/	<b>07/27/2009</b> _____ Date

<b>1. Test item list</b> -----	<b>2</b>
<b>2. Random Vibration Operation Test</b> -----	<b>3</b>

**Test Date:** 07-27-2009

**Test Product:** ONYX-2122

**Test Site:** AAEON QA Internal Lab.

**Test Standard:** Reference IEC68-2-64 Testing procedures

Test Fh: Vibration boardband random test

**Test Equipment:**

Vibration Simulator System

KING DESIGN Co. LTD.


Model: KD 9363-EM-600F2K-40N20

Serial Number: UU110099090

Date of Calibration: 10/16/2008

**Test Condition:**

1. Operation
2. Test Acceleration: 0.5 Grms Random
3. Test Frequency: 5-500Hz
4. Test Axis: X, Y, Z axes
5. Test Time: 60min each axis
6. Test Software: Windows XP / Run one Microsoft media player simultaneously.
7. Test Vibration Curve:



**Test Result:**

No structure deformation was found, and function was working normally.